





General information

Make	VAUXHALL
Model	MERIVA TECH LINE CDTI ECOFLEX S/S
Colour	Black
Year of manufacture	2016
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С





Internet history

Entry 2		
Date	2021-06-29	
Pictures	10	
Listing price	View report	
<section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header>	<section-header></section-header>	where the same can at a lower price, we will refund the difference of the same can at a lower price, we will refund the same can at a lower price, we will refund the same can at a lower price.
Entry 1		
Date	2021-06-15	

Pictures

Listing price

10 View report

FINANCE AVAILABLE

ally trained sales team can offer you a te in minutes on the car of your dream

L Hilton Garage

PROTECT THE MHS SAVELIVES



source: yesauto.com



+£300

We are so confident in our prices We are so confident in our prices that if you find the same car at a lower price, we will refund the difference... PLUS £300

100 05



MOT history

MOT expiry date	2024-07-05
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	6
Total items failed	1

MOT #6	2023-06-19 09:19
MOT test number	547360910618
Result	Passed
Next expiry date	2024-07-05
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #5 2022-06-16 07:40 MOT test number 519537257930 Result ✓ Passed Advice Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

МОТ #4	2021-07-06 10:16
MOT test number	346526636625
Result	✓ Passed
Advice Offside Rear Nail in tyre	





MOT #3	2021-07-05 10:26
MOT test number	229134349746
Result	🗙 Failed
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h) Advice Offside Rear Nail in tyre)
MOT #2	2020-08-20 12:44
MOT test number	216836555537
Result	✓ Passed
MOT #1	2019-04-18 13:34
MOT test number	692777864673
Result	✓ Passed



Tax & MOT check

Tax due: 1 July 2024	✓ Taxed	Expires: 5 July 2024	✓ МОТ
Tax status			Valid until 1 July
Days left			62
MOT expiry date			5 July 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

AND	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-04-28
Last registration	2023-06-19
Complete history	See info



Registration #1	2016-04-28	26 mi
Registration #2	2019-04-18	19.097 mi
Registration #3	2020-08-20	23.631 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi

More info \rightarrow





Safety ratings

NCAP rating	****
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1518 kg
Max. allowed weight	2040 kg
Additional information	
Additional information Fuel tank capacity	54 I
	54 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5