



report date: 2024-03-29

General information

Make	JAGUAR
Model	XK8 COUPE
Colour	Blue
Year of manufacture	2002
Top speed	156 mph
0 - 60 mph	6.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	290 BHP
Max. torque	393 Nm at 4.250 rpm
Engine capacity	3.996 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.7 mpg
Consumption extra urban	31.0 mpg
Consumption combined	23.0 mpg
CO2 emission	281 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-12-08
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-17
MOT pass rate	83 %
MOT passed	19
Failed MOT tests	4
Total advice items	29
Total items failed	9

MOT #23	2023-10-18 10:16
MOT test number	517292875033
Result	✓ Passed
Next expiry date	2024-10-17
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Lower Suspension component mounting prescribed area damaged but not considered excessive sill section (5.3.6 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #22	2022-12-07 14:35
MOT test number	396125085115
Result	✓ Passed
Advice	N/s/r outer sill getting weak
Advice	Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Front inner rack arms play
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #21**

2022-09-26 10:10

MOT test number

573135297138

Result**✗ Failed**

MAJOR Front Seat belt anchorage prescribed area strength or continuity significantly reduced both floors corroded + holed (7.1.1 (a) (i))

Advice Nearside Rear Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill weak (7.1.1 (a) (i))

Advice Front Inner Steering arm deformed but serviceable rack arms slight play (2.1.3 (c) (i))

MAJOR Offside Rear Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill holed (7.1.1 (a) (i))

Advice Rear Coil spring corroded (5.3.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #20

2021-09-09 14:59

MOT test number

998222491495

Result**✓ Passed**

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #19

2020-11-17 12:59

MOT test number

837129651006

Result**✓ Passed****MOT #18**

2019-06-19 12:03

MOT test number

977988497206

Result**✓ Passed****MOT #17**

2018-06-19 11:21

MOT test number

689734307520

Result**✓ Passed**

**MOT #16** 2017-06-19 11:56**MOT test number** 597387311945**Result** ✓ Passed**Advice** Nearside Front tyre worn on inner edge**Advice** Parking brake effort (17%) has only just met the minimum efficiency. It would appear the rear brakes will require attention.**MOT #15** 2016-06-09 10:31**MOT test number** 146292234300**Result** ✓ Passed**MOT #14** 2015-06-16 11:09**MOT test number** 115607865126**Result** ✓ Passed**MOT #13** 2014-06-20 11:48**MOT test number** 875141374105**Result** ✓ Passed**MOT #12** 2013-06-17 14:08**MOT test number** 337408663187**Result** ✓ Passed**MOT #11** 2012-06-13 15:25**MOT test number** 738425762127**Result** ✓ Passed**MOT #10** 2011-06-21 10:38**MOT test number** 215212271120**Result** ✓ Passed**Advice** Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)

**MOT #9** 2010-06-15 15:55**MOT test number** 244476660403**Result** ✓ Passed**MOT #8** 2009-06-11 09:19**MOT test number** 283282669107**Result** ✓ Passed

Advice Nearside Inner Rear Drive shaft uj which forms part of the suspension has slight play in a universal joint (2.4.G.4b)

Advice Offside Front Ball joint has slight play (2.2.B.1f)

Advice Offside Inner Rear Drive shaft uj which forms part of the suspension has slight play in a universal joint (2.4.G.4b)

MOT #7 2009-06-10 11:07**MOT test number** 551251469187**Result** ✗ Failed

Advice Nearside Inner Rear Drive shaft uj which forms part of the suspension has slight play in a universal joint (2.4.G.4b)

Fail Front Brake pipe excessively corroded (3.6.B.2c)

Advice Offside Front Ball joint has slight play (2.2.B.1f)

Advice Offside Inner Rear Drive shaft uj which forms part of the suspension has slight play in a universal joint (2.4.G.4b)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #6 2009-06-02 13:32**MOT test number** 393433459113**Result** ✗ Failed

Fail Nearside Front Sub-frame rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Sub-frame rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #5** 2008-06-03 15:56**MOT test number** 452155058160**Result** ✓ Passed**MOT #4** 2007-06-15 09:52**MOT test number** 370436867158**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2007-03-20 16:54**MOT test number** 334339477070**Result** ✓ Passed**MOT #2** 2007-03-13 16:25**MOT test number** 803632577018**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Front position lamp(s) flickers when tapped lightly by hand (1.1.4c)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2006-03-13 15:08**MOT test number** 931742376020**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
17 October 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	17 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2002-03-25
Last registration	2023-10-18
Complete history	See info



Registration #1	2002-03-25	16 mi
Registration #2	2006-03-13	29.311 mi
Registration #3	2007-03-13	39.033 mi
Registration #4	2007-03-20	39.033 mi
Registration #5	2007-06-15	39.038 mi
Registration #6	2008-06-03	43.128 mi
Registration #7	2009-06-02	46.547 mi
Registration #8	2009-06-10	46.621 mi
Registration #9	2009-06-11	46.622 mi
Registration #10	2010-06-15	50.325 mi
Registration #11	2011-06-21	55.279 mi
Registration #12	2012-06-13	60.499 mi
Registration #13	2013-06-17	65.105 mi
Registration #14	2014-06-20	70.217 mi
Registration #15	2015-06-20	75.329 mi
Registration #16	2016-06-20	80.441 mi
Registration #17	2017-06-20	85.553 mi
Registration #18	2018-06-20	90.665 mi
Registration #19	2019-06-20	95.777 mi
Registration #20	2020-06-20	100.889 mi
Registration #21	2021-06-20	105.999 mi
Registration #22	2022-06-20	111.111 mi
Registration #23	2023-06-20	116.223 mi
Registration #24	2024-06-20	121.335 mi
Registration #25	2025-06-20	126.447 mi



Dimensions & weight

Width	2015 mm
Height	1296 mm
Length	4760 mm
Wheel base	2588 mm
Kerb weight	1615 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	NB0204240121