



KN580FL

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF MATCH TDI 105
Colour	Silver
Year of manufacture	2008
Top speed	116 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	132 g/km
CO2 label	E





MOT history

MOT expiry date	2025-01-12
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	31
Total items failed	2

MOT #15	2024-01-13 13:13
MOT test number	946978918632
Result	✓ Passed
Next expiry date	2025-01-12
Advice	Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

MOT #14	2023-01-07 11:01
MOT test number	993381684223
Result	✓ Passed
Advice	Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Integral body structure is corroded but structural rigidity is not significantly reduced sills (6.1.1 (c) (i))

MOT #13	2023-01-07 11:01
MOT test number	507038537907
Result	✗ Failed
Advice	Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Integral body structure is corroded but structural rigidity is not significantly reduced sills (6.1.1 (c) (i))
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))

**MOT #12**

2022-01-04 13:52

MOT test number

234341075467

Result

✓ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Coil spring corroded all 4 (5.3.1 (b) (i))

MOT #11

2020-12-14 12:17

MOT test number

866690938676

Result

✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Secondary bonnet catch seized
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10** 2020-12-14 12:17**MOT test number** 575530024656**Result** ✗ Failed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Secondary bonnet catch seized**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2019-11-29 16:08**MOT test number** 432345287213**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2018-10-24 08:54**MOT test number** 970838220810**Result** ✓ Passed**Advice** Front wiper blades getting in poor condition**Advice** Front brake pads about 60% worn**Advice** Slight play in offside rear anti roll bar linkage

**MOT #7** 2017-10-17 08:46**MOT test number** 213558224158**Result** ✓ Passed**Advice** Centre exhaust clamp corroded**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2016-09-26 14:03**MOT test number** 264965776808**Result** ✓ Passed**Advice** Engine covers and under trays fitted preventing full inspection**MOT #5** 2015-09-29 12:20**MOT test number** 415893787048**Result** ✓ Passed**MOT #4** 2014-10-02 14:57**MOT test number** 305505274225**Result** ✓ Passed**MOT #3** 2013-10-01 14:33**MOT test number** 448834673236**Result** ✓ Passed**MOT #2** 2012-10-03 09:29**MOT test number** 218167572270**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #1	2011-09-13 12:19
MOT test number	236346451248
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
12 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	12 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KN58OFL
Plate since	2019-06-29
Current registration	 KN58OFL
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-09-29
Last registration	2024-01-13
Complete history	See info



Registration #1	2008-09-29	7 mi
Registration #2	2011-09-13	41.779 mi
Registration #3	2012-10-03	59.220 mi
Registration #4	2013-10-01	74.377 mi
Registration #5	2014-10-02	80.938 mi
Registration #6	2015-09-29	92.818 mi
Registration #7	2016-09-26	103.444 mi
Registration #8	2017-10-17	114.280 mi
Registration #9	2018-05-29	125.277 mi
Registration #10	2019-05-29	135.277 mi
Registration #11	2020-05-29	145.277 mi
Registration #12	2021-05-29	155.277 mi
Registration #13	2022-05-29	165.277 mi
Registration #14	2023-05-29	175.277 mi
Registration #15	2024-01-13	185.277 mi
Registration #16	2024-01-13	195.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1251 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BXE B29276