






General information

Make	CITROEN
Model	C3 DSPORT PLUS
Colour	Silver
Year of manufacture	2014
Top speed	132 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E





MOT history

MOT expiry date	2025-03-24
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	28
Total items failed	1

MOT #10	2024-03-19 12:22
MOT test number	217122263778
Result	✓ Passed
Next expiry date	2025-03-24

МОТ #9		2024-03-19 12:22
MOT test number		718462348498
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))	

MOT #8	2023-03-24 12:04
MOT test number	392943855150
Result	✓ Passed
MOT #7	2022-03-25 13:21

MOT test number	848065704909
Result	✓ Passed



KN64UUH
report date: 2024-03-29

2020-09-28 11:46 315671633108

MOT #6		2020-09-30 14:28
MOT test	number	385188150092
Result		✓ Passed
Advice Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Rear Direction indicator slightly discoloured both (4.4.3 (a))	

MOT #	5
-------	---

МОТ	test	number
-----	------	--------

Result		🗙 Failed
Advice	Rear Direction indicator slightly discoloured both (4.4.3 (a))	
Advice	Offside Rear Nail in tyre	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
MAJOR	Offside Headlamp aim too low (4.1.2 (a))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Offside Headlamp insecure (4.1.1 (c))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2.0mm (5.2.3 (e))	
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #4	2019-09-13	13:05
MOT test	number 48942015	52391
Result	✓ P	assed
Advice	Front number plate damaged	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))	



MOT #3	2019-09-13 10:37	
MOT test number	502290165183	
Result	🗙 Failed	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice Nearside Front Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))	
MAJOR Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))	
DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure outer sidewall (5.2.3 (d) (ii))		
Advice Exhaust mounting defective rear bracket adrift (6.1.2 (a))		
Advice Front number plate damaged		

MOT #2	2018-09	9-25 10:11
MOT test	number 6733	32366586
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Exhaust rear bracket bottom weld adrift	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm and perished (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #1	2017-09-19 10:26
MOT test number	813895889621
Result	✓ Passed

KN64UUH

report date: 2024-03-29



Tax & MOT check

✓ Taxed	✓ MOT Expires:
1 April 2025	Expires: 24 March 2025
Tax status	Valid until 1 April
Days left	336
MOT expiry date	24 March 2025
Full MOT history	<u>See MOT history</u>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lawer
Туре	(*******	
Damage 2		AMPLE
Damage 2		E CONTRACTOR
Date		
Category		AMP
Туре		

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



KN64UUH report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-09-30
Last registration	2024-03-19
Complete history	<u>See info</u>



Registration #1	2014-09-30	12 mi
Registration #2	2017-09-19	18.355 mi
Registration #3	2018-09-25	23.637 mi
Registration #4	2019-09-13	27.413 mi
Registration #5	2019-09-13	27.413 mi
Registration #6	2020-09-28	30.333 mi
Registration #7		11.777 mi
Registration #8		11.777 mil
Registration #9		11.777 mi
Registration #10		11.227 mil
Registration #11		10.000 mi





Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1619 kg
Additional information	
Additional information Fuel tank capacity	48 I
	48 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 3