





General information

Make	RENAULT
Model	TRAFIC LL29 BUSINESS ENERGY DCI
Colour	Silver
Year of manufacture	2015
Top speed	95 mph
0 - 60 mph	15.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	260 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	44.8 mpg
CO2 emission	164 g/km
CO2 label	G







Internet history		
Entry 1		
Date	2021-11-01	
Pictures	0	
Listing price	View report	

source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-19
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #8		2023-12-13 10:32
MOT test r	number	375926842239
Result		✓ Passed
Next expir	y date	2024-12-19
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))	

MOT #7	2022-12-20 12:12
MOT test number	635297223661
Result	✓ Passed
Advice Items removed from driver's view prior to testAdvice Nearside Rear Outer Seat belt slightly damaged (7.1.2 (b) (i))	
Advice Nearside Rear Outer Seat Beit slightly damaged (7.1.2 (b) (i))	

МОТ #6		2022-12-20 12:12
MOT test number		398925233123
Result		🗙 Failed
Advice Items removed t	rom driver's view prior to test	
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))	
Advice Nearside Rear Outer Seat belt slightly damaged (7.1.2 (b) (i))		





MOT #5	2021-11-22 12:49
MOT test number	765058811342
Result	✓ Passed
MOT #4	2021-03-18 11:57
MOT test number	710671901567
Result	✓ Passed

MOT #3		2019-10-10 10:37
MOT test	number	129390307934
Result		✓ Passed
Advice	Nearside Rear Seat belt slightly damaged centre row (7.1.2 (b) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2		2019-10-10 10:02
MOT test	number	596666144933
Result		🗙 Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Seat belt slightly damaged centre row (7.1.2 (b) (i))		
Fail N	earside Rear Tyre has a lump, caused by separation or partial failure of its struct	ture (5.2.3 (d) (ii))

MOT #1	2018-10-23 10:19
MOT test number	360169721689
Result	✓ Passed
Advice Rear Tyre slightly damaged both (5.2.3 (d) (ii))	



Tax & MOT check

✓ Taxed	√ мот
Tax due: 1 December 2024	Expires: 19 December 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	
Category	 AMPL
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

NUMBER OF TAXABLE	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-11-24
Last registration	2023-12-13
Complete history	See info



Registration #1	2015-11-24	6 mi
Registration #2	2018-10-23	33.974 mi
Registration #3	2019-10-10	35.587 mi
Registration #4	2019-10-10	35.587 mi
Registration #5	2021-03-18	36.138 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight	
Width	2283 mm
Height	1971 mm
Length	5399 mm
Kerb weight	1923 kg
Max. allowed weight	3010 kg
Additional information	
Fuel tank capacity	80 I

Fuel tank capacity	80	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	9	
Number of axles CarCheck.co.uk	2	page 11/11

Engine number

C000948