





report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SPORT
Colour	Black
Year of manufacture	-
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	366 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-28


Internet history

Entry 2


Date 2021-12-26

Pictures 31

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-12-25
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT #21 2021-05-04 12:42

MOT test number 725663438497

Result ✓ Passed

Next expiry date 2022-05-03

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #20 2021-03-03 11:50

MOT test number 995718806331

Result X Failed

Minor Offside Front Brake hose slightly chafed (1.1.12 (b) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened offside front and nearside front inner friction surfaces corroded (1.1.14 (a) (ii))

Fail Suspension component mounting prescribed area excessively corroded significantly reducing structural strength offside rear & nearside rear outer sills (5.3.6 (a) (i))

Fail Fuel pipe leaking (6.1.3 (b) (i))

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #19 2020-02-26 14:06

MOT test number 642839834757

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Fuel Pipe/s corroded

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #18 2020-02-25 15:58

MOT test number 573430603911

Result X Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Fuel Pipe/s corroded

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #17 2019-02-05 11:31

MOT test number 922846299520

Result \rightarrow Passed

Advice Offside Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2018-02-28 12:15

MOT test number 330224941321

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

MOT #15 2018-02-28 12:15

MOT test number 145107568456

Result X Failed

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

CarCheck.co.uk page 4/13



PV55EXM report date: 2024-03-28

MOT #14 2017-02-27 08:41

MOT test number 540172843303

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered

excessive (2.4.A.3)

Advice Nail in o/s/r tyre

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #13 2016-02-18 14:28

MOT test number 609590299418

Result \sqrt{Passed}

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Offside Rear coil spring corroded (2.4.C.1b)

MOT #12 2015-02-24 12:53

MOT test number 577555755094

Result ✓ Passed

MOT #11 2015-02-24 08:43

MOT test number 286675855011

Result X Failed

Fail Nearside Front coil spring broken (2.4.C.1a)

MOT #10 2014-02-19 14:10

MOT test number 538160154061

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #9 2014-02-19 08:36

MOT test number 205080254035

Result X Failed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)

MOT #8 2013-02-20 08:34

MOT test number 966171353018

Result ✓ Passed

MOT #7 2013-02-20 08:34

MOT test number 265121853089

Result X Failed

Pass with rectification Exhaust has a major leak of exhaust gases (7.1.2)

MOT #6 2012-02-17 09:50

MOT test number 105798242415

Result

Passed

MOT #5 2012-02-17 09:50

MOT test number 107938142018

Result X Failed

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Offside Track rod end has had excessive heat applied (2.2.C.1e)

MOT #4 2011-02-08 08:46

MOT test number 645879131044

CarCheck.co.uk page 6/13



report date: 2024-03-28

MOT #3	2010-02-09 08:45
MOT test number	850290140072
Result	✓ Passed
MOT #2	2009-03-05 16:33
MOT test number	272344769039
Result	✓ Passed
MOT #1	2009-02-12 14:43
MOT test number	381193449031
Result	✓ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



PV55EXM report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
manus .	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	OK SILE
Plate since	
Current registration	AK NY
Plate since	
	More info >

CarCheck.co.uk page 10/13



PV55EXM report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 11/13



PV55EXM report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-12-15
Last registration	2021-05-04
Complete history	See info



Registration #1	2005-12-15	28 mi
Registration #2	2009-02-12	112.289 mi
Registration #3	2009-03-05	112.298 mi
Registration #4	2010-02-09	118.866 mi
Registration #5	2011-02-08	125.360 mi
Registration #6	2012-02-17	132.399 mi
Registration #7	2013-02-20	136.731 mi
Registration #8	2014-02-19	139.490 mi
Registration #9	2014-02-19	139.490 mi
Registration #10	2015-02-24	143.538 mi
Registration #11	2015-02-24	143.538 mi
Registration #12		11.777 ea
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 12/13



PV55EXM report date: 2024-03-28

Safety ratings

NCAP rating	****
-------------	------

Video <u>see crash video</u>



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1575 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	051028161728BG

CarCheck.co.uk page 13/13