



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE AUTHENTIQUE VVT 111
Colour	Gold
Year of manufacture	2006
Top speed	119 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	152 Nm at 4.200 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.9 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-28
Pictures	16
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-16
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	88
Total items failed	20

MOT #23	2023-07-21 07:41
MOT test number	508796219872
Result	✓ Passed
Next expiry date	2024-08-16

MOT #22	2022-08-03 16:24
MOT test number	143959779044
Result	✓ Passed

- Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Engine poor running
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21**

2022-08-03 10:21

**MOT test number**

673933211278

**Result****✗ Failed**

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Engine poor running
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #20**

2021-08-17 15:25

**MOT test number**

157848848924

**Result****✓ Passed**

**MOT #19**

2021-08-03 16:02

**MOT test number**

892402725342

**Result****✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Play in steering rack inner joint(s)
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))

**MOT #18**

2020-12-07 11:10

**MOT test number**

854138600869

**Result****✓ Passed**

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))



MOT #17

2020-12-03 10:19

MOT test number

454203337966

Result		✗ Failed
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice	Offside Front Play in steering rack inner joint(s)	
Fail	Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm tread depth (5.2.3 (e))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2mm tread depth (5.2.3 (e))	



MOT #16

2019-06-01 11:31

MOT test number

728866296169

Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Brake disc worn, but not excessively o/s n/s (1.1.14 (a) (i))	
Advice	Nearside Rear brake pipe on axle slightly corroded	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Coil spring corroded o/s n/s (5.3.1 (b) (i))	
Advice	Nearside Front Play in steering rack inner joint(s)	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

**MOT #15**

2019-05-31 10:53

**MOT test number**

813175405426

**Result****✗ Failed**

- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, but not excessively o/s n/s (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear brake pipe on axle slightly corroded
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Coil spring corroded o/s n/s (5.3.1 (b) (i))

**MOT #14**

2018-06-08 15:56

**MOT test number**

252526168610

**Result****✓ Passed**

- Advice** Offside Rear tail light slightly affected by another light
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Play in steering rack inner joint(s) o/s n/s
- Advice** Rear Brake disc worn, but not excessively o/s n/s (1.1.14 (a) (i))



**MOT #13** 2018-05-30 08:50**MOT test number** 890812399610**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp light intensity severely reduced image (4.1.4 (a))**Advice** Play in steering rack inner joint(s) o/s n/s**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear tail light slightly affected by another light**Advice** Rear Brake disc worn, but not excessively o/s n/s (1.1.14 (a) (i))**Fail** Nearside Rear Brake pipe excessively corroded on axle (1.1.11 (c))**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**MOT #12** 2017-05-23 13:13**MOT test number** 252906560052**Result** ✓ Passed**MOT #11** 2017-05-22 14:11**MOT test number** 312837331773**Result** ✗ Failed**Fail** Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)**Fail** Nearside Stop lamp not working (1.2.1b)



MOT #10	2016-10-24 14:16
MOT test number	276793512978
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
Advice	Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9	2016-10-24 11:07
MOT test number	144544778860
Result	✗ Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
Fail	Offside Rear Brake pipe excessively damaged (3.6.B.2c)
Advice	Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2015-10-24 10:03**MOT test number** 381487788521**Result** ✓ Passed**Advice** Under tray fitted**Advice** Child seats fitted**MOT #7** 2015-10-24 10:03**MOT test number** 307089959222**Result** ✗ Failed**Advice** Under tray fitted**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Child seats fitted**MOT #6** 2014-10-25 09:25**MOT test number** 375768894261**Result** ✓ Passed**MOT #5** 2013-10-31 13:25**MOT test number** 739314303397**Result** ✓ Passed**Notice** Not tested rear seatbelts (child seats fitted)**MOT #4** 2012-11-02 10:41**MOT test number** 966847002305**Result** ✓ Passed**Notice** Not tested nearside rear seatbelt (childseat fitted)

**MOT #3** 2011-10-27 11:32**MOT test number** 486040901486**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-11-04 11:05**MOT test number** 690538100396**Result** ✓ Passed**Notice** Not tested nearside rear seatbelt (childseat fitted)**MOT #1** 2009-07-22 09:07**MOT test number** 510723009212**Result** ✓ Passed**Notice** Wear to front brake discs and pads**Notice** All tyres (sidewalls starting to crack)**Notice** Inner rear brake pads wearing



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
16 August 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	16 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-07-27
Last registration	2023-07-21
Complete history	<a href="#">See info</a>



Registration #1	2006-07-27	28 mi
Registration #2	2009-07-22	16.988 mi
Registration #3	2010-11-04	24.122 mi
Registration #4	2011-10-27	28.539 mi
Registration #5	2012-11-02	33.848 mi
Registration #6	2013-10-31	39.630 mi
Registration #7	2014-10-25	47.831 mi
Registration #8	2015-10-24	56.902 mi
Registration #9	2015-10-24	56.902 mi
Registration #10	2016-10-24	64.936 mi
Registration #11	2016-10-24	64.936 mi
Registration #12	2017-05-22	67.014 mi
Registration #13	2017-05-23	67.014 mi
Registration #14	2018-05-22	75.117 mi
Registration #15	2018-05-22	75.117 mi
Registration #16	2018-05-22	75.117 mi
Registration #17	2018-05-22	75.117 mi
Registration #18	2018-05-22	75.117 mi
Registration #19	2018-05-22	75.117 mi
Registration #20	2018-05-22	75.117 mi
Registration #21	2018-05-22	75.117 mi
Registration #22	2018-05-22	75.117 mi
Registration #23	2018-05-22	75.117 mi
Registration #24	2018-05-22	75.117 mi
Registration #25	2018-05-22	75.117 mi



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2039 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

NOT KNOWN