



report date: 2024-03-28

General information

Make	MAZDA
Model	5 FURANO
Colour	Blue
Year of manufacture	2010
Top speed	110 mph
0 - 60 mph	13.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg
CO2 emission	187 g/km
CO2 label	J







Internet history

Entry 1

Date	2022-05-17
Pictures	28
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-24
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	39
Total items failed	3

MOT #14 2023-06-16 09:08

MOT test number 454789682221

Result ✓ Passed

Next expiry date 2024-06-24

- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** General under body and suspension corrosion

MOT #13 2022-06-01 13:46

MOT test number 112620004192

Result ✓ Passed



MOT #12	2022-05-31 16:29
MOT test number	133253649846
Result	✗ Failed
MAJOR	Offside Front Lower Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))
MAJOR	Nearside Front Lower Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))

MOT #11	2021-06-17 12:09
MOT test number	844567200301
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view Stone Chips (3.2 (a) (i))
Advice	Fuel hose deteriorated return from tank (6.1.3 (c) (ii))
Advice	Coil spring corroded All (5.3.1 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2020-06-25 07:36
MOT test number	423931017554
Result	✓ Passed
Advice	Coil spring corroded Front and rear (5.3.1 (b) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9	2019-04-17 13:35
MOT test number	599117993173
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8**

2018-04-12 09:15

MOT test number

299386103283

Result

✓ Passed

- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Nail in tyre

MOT #7

2018-04-12 09:15

MOT test number

227269488578

Result

✗ Failed

- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Nail in tyre
- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6

2017-04-03 16:03

MOT test number

879976100243

Result

✓ Passed

- Advice** Rear coil spring corroded both sides (2.4.C.1b)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement leading)(BORDERLINE (2.4.G.2)
- Advice** Front coil spring corroded both sides (2.4.C.1b)
- Advice** Child seat fitted to offside middle row seat, seat belt not fully tested
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement leading)(BORDERLINE (2.4.G.2)

**MOT #5** 2017-04-03 12:49**MOT test number** 425312203938**Result** ✗ Failed

Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Child seat fitted to offside middle row seat, seat belt not fully tested

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement leading)(BORDERLINE (2.4.G.2)

Advice Rear coil spring corroded both sides (2.4.C.1b)

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement leading)(BORDERLINE (2.4.G.2)

MOT #4 2016-03-29 08:32**MOT test number** 803938198115**Result** ✓ Passed

Advice ADVANCED corrosion to exhaust hanger/s

Advice Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement trailing bushes, both sides (2.4.G.2)

Advice NOTE- Child seat fitted to offside seat middle row, seat/belt not fully tested

MOT #3 2015-04-07 15:25**MOT test number** 339527395071**Result** ✓ Passed**MOT #2** 2014-04-10 10:47**MOT test number** 385780104130**Result** ✓ Passed**MOT #1** 2013-04-19 11:55**MOT test number** 868119303131**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
24 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	24 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-23
Last registration	2023-06-16
Complete history	See info



Registration #1	2010-03-23	16 mi
Registration #2	2013-04-19	14.214 mi
Registration #3	2014-04-10	19.840 mi
Registration #4	2015-04-07	24.730 mi
Registration #5	2016-03-29	32.169 mi
Registration #6	2017-04-03	39.928 mi
Registration #7	2017-04-03	39.928 mi
Registration #8	2018-04-12	48.464 mi
Registration #9	2019-05-20	55.277 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1410 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	LF 10895894