



report date: 2024-03-28

General information

Make	CITROEN
Model	C5 HDI VT
Colour	Grey
Year of manufacture	2009
Top speed	94 mph
0 - 60 mph	17.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	185 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-12-09
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-12-08
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	53
Total items failed	22

MOT #18	2022-12-07 15:50
MOT test number	416961849521
Result	✓ Passed
Next expiry date	2023-12-08
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #17**

2022-12-05 13:37

**MOT test number**

648336645975

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Minor** Nearside Rear Inner Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Seat belt retracting mechanism defective (7.1.2 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Trailer electrical socket (13 pin) not operating the trailer lamps as intended Brake lamp (4.10 (c) (i))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Auxiliary drive belt missing
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #16**

2021-12-09 11:12

**MOT test number**

398838119976

**Result**

✓ Passed

**Advice** All under body and components corroded**Advice** All under body cover fitted**Advice** O/S/F shock slightly leaking**MOT #15**

2021-12-08 17:18

**MOT test number**

486041157774

**Result**

✗ Failed

**Advice** O/S/F shock slightly leaking**Fail** Offside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** All under body and components corroded**Advice** All under body cover fitted**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #14**

2021-02-17 09:56

**MOT test number**

341988352247

**Result**

✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13**

2020-02-19 11:56

**MOT test number**

572359953396

**Result**

✓ Passed

**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #12** 2019-02-12 09:58**MOT test number** 710058387917**Result** ✓ Passed**MOT #11** 2018-02-19 12:43**MOT test number** 522522995555**Result** ✓ Passed**Advice** Rear brake discs inner faces corroded**MOT #10** 2018-02-19 10:06**MOT test number** 363049573653**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear brake discs inner faces corroded**MOT #9** 2017-02-08 11:57**MOT test number** 642946144855**Result** ✓ Passed**Advice** FRONT AND REAR SUSPENSION BUSHES DETERIORATED**Advice** ADVANCED CORROSION REAR ANTIROLL BAR**MOT #8** 2016-02-16 14:12**MOT test number** 243874083014**Result** ✓ Passed

**MOT #7** 2016-02-16 14:12**MOT test number** 800186604663**Result** ✗ Failed**Pass with rectification** Nearside Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2015-02-24 13:08**MOT test number** 707565055075**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2015-02-17 10:47**MOT test number** 148758345049**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #4

2014-02-08 11:48

MOT test number

957579734060

Result		✓ Passed
Notice	Advance play in n/s/f track rod end ball joint	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Sills covered	
Notice	Dampness around fuel tank	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Vehicle's internal headlight adjuster altered to recheck lights	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Stone chips in windscreen	
Notice	Exhaust corroded	
Notice	Items removed from driver's view prior to test	

**MOT #3** 2014-02-01 11:32**MOT test number** 108232634487**Result** ✗ Failed

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Sills covered
- Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Notice** Dampness around fuel tank
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Stone chips in windscreen
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Notice** Exhaust corroded
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Items removed from driver's view prior to test
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2013-02-09 13:55**MOT test number** 548240943070**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Play in both front lower ball joints

**MOT #1** 2012-02-10 11:16**MOT test number** 767111042096**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
30 September 2023

X

MOT

Expired:  
8 December 2023

Tax status	Expired at 30 September
Days left	211 days too late
MOT expiry date	8 December 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>SH58NNO</b>
Plate since	2019-03-28
Current registration	<b>SH58NNO</b>
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-02-24
Last registration	2022-12-07
Complete history	<a href="#">See info</a>



Registration #1	2009-02-24	19 mi
Registration #2	2012-02-10	112.091 mi
Registration #3	2013-02-09	121.252 mi
Registration #4	2014-02-01	130.476 mi
Registration #5	2014-02-08	130.487 mi
Registration #6	2015-02-17	137.296 mi
Registration #7	2015-02-24	137.296 mi
Registration #8	2016-02-16	138.449 mi
Registration #9	2016-02-16	138.449 mi
Registration #10	2017-02-08	140.595 mi
Registration #11	2018-02-08	140.595 mi
Registration #12	2018-02-08	140.595 mi
Registration #13	2018-02-08	140.595 mi
Registration #14	2018-02-08	140.595 mi
Registration #15	2018-02-08	140.595 mi
Registration #16	2018-02-08	140.595 mi
Registration #17	2018-02-08	140.595 mi
Registration #18	2018-02-08	140.595 mi
Registration #19	2018-02-08	140.595 mi
Registration #20	2018-02-08	140.595 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1407 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBBU3099403