






report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 260 SWB P/V
Colour	White
Year of manufacture	2003
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	180 Nm at 2.250 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	39.8 mpg
Consumption combined	34.9 mpg



CarCheck.co.uk page 1/11



VK53BEY report date: 2024-03-29

MOT history

MOT expiry date	2021-09-08
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	12
Total items failed	13

MOT test number Result	826619029467
Result	
	✓ Passed
Next expiry date	2021-09-08
Advice Offside Rear Vehicle structure is corroded but structural rigidity is not sign rear axle (6.1.1 (c) (i)) Advice Nearside Rear Vehicle structure is corroded but structural rigidity is not sign rear axle (6.1.1 (c) (i))	-

MOT #19	2020-08-27 08:47
MOT test number	220101183831
Result	× Failed
Advice Offside Rear Vehicle structure is corroded but structural rigidity is not signific rear axle (6.1.1 (c) (i))	antly reduced over
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Nearside Rear Vehicle structure is corroded but structural rigidity is not signif rear axle (6.1.1 (c) (i))	icantly reduced over

MOT #18	2019-08-09 09:35
MOT test number	332956491640
Result	✓ Passed
MOT #17	2018-09-07 10:54
MOT test number	363291371713
Result	✓ Passed

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT #16 2017-09-06 10:52

MOT test number 333171707837

Advice

Nearside Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)

MOT #15 2016-09-08 10:54

MOT test number 255728255856

Result ✓ Passed

MOT #14 2016-09-08 10:54

MOT test number 362350447299

Result X Failed

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #13 2015-09-07 14:17

MOT test number 354593523485

Result

Passed

MOT #12 2015-09-07 14:17

MOT test number 222659395597

Result × Failed

Pass with rectification Offside Stop lamp not working (1.2.1b)

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #11

MOT test number

Result

Notice Wiper blades deteriating.

MOT #10

MOT test number

488817844228

Result

Pass with rectification

Offside Stop lamp not working (1.2.1b)

Notice

Wiper blades deteriating.

Pass with rectification

Offside Rear position lamp(s) not working (1.1.A.3b)

MOT #9

MOT test number

Result

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT test number

Result

Pass with rectification

Offside Rear position lamp(s) not working (1.1.A.3b)

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Pass with rectification

Nearside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification

Offside Rear Stop lamp not working (1.2.1b)

MOT #7

MOT test number

659629242386

Result

✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #6 2011-12-13 08:44

MOT test number 669607641333

Result ✓ Passed

MOT #5 2010-12-13 17:06

MOT test number 124117640383

Result

Passed

MOT #4 2009-12-11 12:37

MOT test number 464435549493

Result \(\sqrt{Passed} \)

MOT #3 2008-01-03 12:14

MOT test number 720503908033

Result \(\sqrt{Passed} \)

Advice Nearside Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2006-09-06 11:03

MOT test number 980929146262

Result ✓ Passed

Advice Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1 2006-09-06 11:03

MOT test number 253889946248

Result × Failed

Pass with rectification Nearside Headlamp aim too low (1.8)

Advice Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Pass with rectification Offside Headlamp aim too low (1.8)

CarCheck.co.uk page 5/11



VK53BEY report date: 2024-03-29

Tax & MOT check



X MOT

Expired: 8 September 2021

Tax status Expired at 27 January 2021

Days left 1189 days too late

MOT expiry date 8 September 2021

Full MOT history See MOT history

CarCheck.co.uk page 6/11



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra FORD salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners defined the current and see all owner registrations. Download the full report be a second to the full r	
manage of the same	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	IK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



/K53BEY

report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



VK53BEY report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2003-09-12
Last registration	2020-08-28
Complete history	See info



Registration #1	2003-09-12	22 mi
Registration #2	2006-09-06	11.964 mi
Registration #3	2008-01-03	15.038 mi
Registration #4	2009-12-11	20.735 mi
Registration #5	2010-12-13	27.666 mi
Registration #6	2011-12-13	36.109 mi
Registration #7	2012-12-14	45.877 mi
Registration #8	2013-09-09	51.181 mi
Registration #9	2014-09-04	56.162 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 10/11



VK53BEY report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

		_		
Dim	ensior	יכ צי	MAIG	ht
ווווט	CHOIDE	IS CX	WCIU	IIIL

Width	2360 mm
Height	1970 mm
Length	4834 mm

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Engine number	3U22192

CarCheck.co.uk page 11/11