





report date: 2024-03-29

## General information

Make	VOLKSWAGEN
Model	GOLF S TSI
Colour	Blue
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	122 BHP
Max. torque	200 Nm at 1.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg



CarCheck.co.uk page 1/10



report date: 2024-03-29

# Internet history

## Entry 1

Date 2021-06-03

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

# MOT history

MOT #13	2022-06-14 13:01
MOT test number	481740770286
Result	✓ Passed
Next expiry date	2023-06-13
MOT #12	2021-06-12 16:13
MOT test number	498829877031
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2020-11-02 15:29
MOT test number	635067233483
Result	✓ Passed

MOI #10	2020-01-27 10:49
MOT test number	243763716755
Result	<b>✓</b> Passed

MOT #9	2019-05-07 13:15
MOT test number	544296622523
Result	.✓ Passed

MOT #8	2018-03-13 11:12
MOT test number	258838417086
Result	✓ Passed

MOT #7	2018-03-13 09:52
MOT test number	340696918378
Result	<b>X</b> Failed
Fail Rear fog lamp not working (1.3.2b)	

CarCheck.co.uk page 3/10



report date: 2024-03-29

MOT #6 2017-03-21 17:02

**MOT test number** 567988805990

MOT #5 2016-05-09 09:00

**MOT test number** 942750574238

Result 

✓ Passed

MOT #4 2015-05-18 10:50

MOT test number 848008035163

**Result** 
✓ Passed

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2014-06-16 15:28

**MOT test number** 206317864180

Result \( \sqrt{Passed} \)

MOT #2 2013-06-25 12:13

MOT test number 258356473467

Result \( \sqrt{Passed} \)

**Notice** Under-trays fitted obscuring some underside components

**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #1** 2013-01-21 15:24

**MOT test number** 579541023099

**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/10



report date: 2024-03-29

## Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	

#### Damage 2

Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

More info >

# Owner history

Owner matery	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	NE SIE
Plate since	
Current registration	OK SIE
Plate since	

CarCheck.co.uk page 7/10



report date: 2024-03-29

## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 8/10



NX10PTO report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-01
Last registration	2022-06-14
Complete history	See info



Registration #1	2010-03-01	19 mi
Registration #2	2013-01-21	24.924 mi
Registration #3	2013-06-25	27.059 mi
Registration #4	2014-06-16	32.296 mi
Registration #5	2015-05-18	41.217 mi
Registration #6	2016-05-09	50.002 mi
Registration #7	2017-03-21	58.027 mi
Registration #8	2018-03-13	65.752 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.777 es

More info >

CarCheck.co.uk page 9/10



NX10PTO report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1215 kg
Max. allowed weight	1850 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChack co.uk	page 10/10

CarCheck.co.uk page 10/10

Number of seats	5
Number of axles	2
Engine number	CAX 290226