



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN

**MOT history**

MOT #15	2023-04-26 07:37
MOT test number	573926863791
Result	✓ Passed
Next expiry date	2024-04-25

MOT #14	2023-04-21 12:16
MOT test number	538916250599
Result	✗ Failed

Fail Nearside Front Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

MOT #13	2022-04-13 12:59
MOT test number	463535531272
Result	✓ Passed

MOT #12	2021-03-08 10:23
MOT test number	631961154567
Result	✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2020-06-04 09:00
MOT test number	200840859307
Result	✓ Passed

MOT #10	2019-06-05 11:41
MOT test number	790917760026
Result	✓ Passed

**MOT #9** 2019-06-05 09:14**MOT test number** 589485010727**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Rear Shock absorbers has an excessively worn bush both sides (5.3.2 (c))**MOT #8** 2018-06-01 14:34**MOT test number** 195866751008**Result** ✓ Passed**MOT #7** 2017-06-03 10:02**MOT test number** 329127662798**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-05-31 09:34**MOT test number** 280962299607**Result** ✓ Passed**MOT #5** 2015-06-03 13:19**MOT test number** 269644655483**Result** ✓ Passed**Notice** BRAKE PIPES UNDER PLASTIC COVERS

**MOT #4** 2015-06-01 17:10**MOT test number** 216992155138**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** BRAKE PIPES UNDER PLASTIC COVERS**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2014-08-08 14:10**MOT test number** 465060324246**Result** ✓ Passed**MOT #2** 2013-05-07 09:41**MOT test number** 765117423132**Result** ✓ Passed**Notice** Back box exhaust deteriorated**Notice** Oil leak**MOT #1** 2013-05-02 12:15**MOT test number** 968602723140**Result** ✗ Failed**Notice** Back box exhaust deteriorated**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Oil leak**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	NX10VXV
Plate since	2019-03-28
Current registration	NX10VXV
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-30
Last registration	2023-04-26
Complete history	See info



Registration #1	2010-03-30	24 mi
Registration #2	2013-05-02	14.617 mi
Registration #3	2013-05-07	14.671 mi
Registration #4	2014-08-08	21.448 mi
Registration #5	2015-06-01	26.199 mi
Registration #6	2015-06-03	26.199 mi
Registration #7	2016-05-31	31.403 mi
Registration #8	2017-06-03	37.292 mi
Registration #9	2018-05-29	38.377 mi
Registration #10	2019-05-29	39.377 mi
Registration #11	2020-05-29	40.377 mi
Registration #12	2021-05-29	41.377 mi
Registration #13	2022-05-29	42.377 mi
Registration #14	2023-05-29	43.377 mi
Registration #15	2024-05-29	44.377 mi
Registration #16	2025-05-29	45.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5775203