





report date: 2024-03-29

#### General information

Make	HONDA
Model	ACCORD VTEC EXECUTIVE
Colour	Black
Year of manufacture	2005
Top speed	134 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	153 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	44.8 mpg
Consumption combined	34.0 mpg
CO2 emission	196 g/km
CO2 label	J



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

#### Entry 2

Date 2021-09-24

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-09-24

Pictures 50

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

# MOT history

MOT expiry date	2023-10-21
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	23
Total items failed	9

MOT #21		2022-10-17 16:18
MOT test	number	998583590802
Result		✓ Passed
Next expi	ry date	2023-10-21
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement	(5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
<b>Advice</b> (5.3.6 (a) (	Rear Suspension component mounting prescribed area is corroded but not (i))	considered excessive

MOT #20	2022-10-17 14:30
MOT test number	204196179724
Result	<b>X</b> Failed
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice Rear Suspension component mounting prescribed area is corroded but not cons (5.3.6 (a) (i))	sidered excessive
Fail Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.	3.4 (a) (i))
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #19** 2021-10-22 12:31

**MOT test number** 114360508987

**Result** 
✓ Passed

**MOT #18** 2021-09-28 11:15

**MOT test number** 678043858575

**Result** X Failed

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #17** 2021-06-01 12:12

**MOT test number** 414073003585

**Result** X Failed

Fail Front Headlamp aim too low (4.1.2 (a))

**Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #16** 2019-05-20 16:40

**MOT test number** 567658486764

Result 

Passed

**Advice** (under the vehicle genral corrosion)

CarCheck.co.uk page 4/13



Pass with rectification

SP05KHC

report date: 2024-03-29

MOT #15	2018-03-29 13:59
MOT test number	977494798024
Result	✓ Passed
MOT #14	2018-03-29 13:59
MOT test number	442786527812
Result	<b>▼</b> Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #13	2017-03-30 17:05
MOT test number	903742036752
Result	✓ Passed
MOT #12	2016-03-30 17:40
MOT test number	152639347147
Result	✓ Passed
MOT #11	2015-02-13 18:09
MOT test number	178584245495
Result	✓ Passed
MOT #10	2015-02-13 18:09
MOT test number	199734345087
Result	<b>×</b> Failed

MOT #9	2014-03-04 12:37
MOT test number	285143964000
Result	✓ Passed

Horn not working (1.6.2a)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #8 2014-02-24 14:42

**MOT test number** 785145554093

Result × Failed

Fail Nearside Front Front suspension has excessive play in a upper suspension ball joint (2.5.B.1a)

Fail Offside Front Front suspension has excessive play in a upper suspension ball joint (2.5.B.1a)

MOT #7 2013-02-28 15:15

MOT test number 238199153012

**Result** 
✓ Passed

MOT #6 2013-02-28 09:02

**MOT test number** 368039653018

Result X Failed

**Fail** Offside Front Anti-roll bar linkage fractured (2.4.G.1)

MOT #5 2012-03-02 16:33

**MOT test number** 779982562074

**Result** 
✓ Passed

MOT #4 2011-03-25 11:31

**MOT test number** 106424981452

MOT #3 2010-04-15 12:46

**MOT test number** 811225500123

Result \rightarrow Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

MOT #2 2009-04-03 10:20 **MOT test number** 140603599021 Result ✓ Passed Notice Nail in offside rear tyre Nearside Headlamp not in a clean condition but not affecting beam image (1.2.4a) Advice Notice Offside wiper torn - still clearing screen Advice Rear Brake pad(s) wearing thin (3.5.1g) Notice Nearside rear tyre worn on inner edge Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2008-04-16 13:18
MOT test number	840647308118
Result	✓ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



factor scincol

SP05KHC

report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this HONDA had different number plates. deer of plates

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-03-23
Last registration	2022-10-17
Complete history	See info



Registration #1	2005-03-23	18 mi
Registration #2	2008-04-16	13.343 mi
Registration #3	2009-04-03	23.552 mi
Registration #4	2010-04-15	33.496 mi
Registration #5	2011-03-25	43.321 mi
Registration #6	2012-03-02	52.126 mi
Registration #7	2013-02-28	57.791 mi
Registration #8	2013-02-28	57.791 mi
Registration #9	2014-02-24	64.937 mi
Registration #10	2014-03-04	65.030 mi
Registration #10		
Registration #11	2015-02-13	73.206 mi
•	2015-02-13 2016-03-30	73.206 mi 81.064 mi
Registration #11		
Registration #11 Registration #12	2016-03-30	
Registration #11 Registration #12 Registration #13	2016-03-30	
Registration #11 Registration #12 Registration #13 Registration #14	2016-03-30	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	2016-03-30	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2016-03-30	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17	2016-03-30	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18	2016-03-30	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19	2016-03-30	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20	2016-03-30	

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Safety ratings

NCAP rating	****
-------------	------

**Video** <u>see crash video</u>



# Dimensions & weight

Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Kerb weight	1434 kg

# Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	K20A63009181

CarCheck.co.uk page 13/13