





report date: 2024-03-29

General information

Make	MAZDA
Model	3 TS2
Colour	Red
Year of manufacture	2011
Top speed	114 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-01-21
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	13
Total items failed	2

MOT #11	2024-01-17 14:48
MOT test number	898320220044
Result	✓ Passed
Next expiry date	2025-01-21

MOT #10		2024-01-16 13:40
MOT test	number	636560378020
Result		X Failed
MAJOR	Exhaust has a major leak of exhaust gases (6.1.2 (a))	

MOT #9	2023-01-19 16:16
MOT test number	910823046883
Result	✓ Passed

MOT #8	2023-01-18 10:03

MOT test number 728753031334

Result × Failed

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2022-01-22 12:59

MOT test number 376936737830

Result ✓ Passed

Minor

Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #6 2018-09-27 08:36

MOT test number 155947551114

Result \rightarrow Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Exhaust mounting defective support bracket corroded from exhaust at rear silencer. (6.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2017-09-26 11:49

MOT test number 207737289780

Result

Passed

Advice Offside Rear Nail in tyre

Advice Vehicle has under body and sill covers fitted.

MOT #4 2016-09-29 08:50

MOT test number 560783397529

Result
✓ Passed

Advice Under Trays Fitted.

MOT #3 2015-09-30 09:08

MOT test number 253773816729

Result J Passed

Advice Both front and offside rear tyres very badly worn on inner tread bands,in a dangerous condition

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #2 2015-09-30 09:08

MOT test number 743091799823

Result X Failed

Advice Both front and offside rear tyres very badly worn on inner tread bands,in a dangerous condition

Pass with rectification within zone 'A' (8.3.1b)

Windscreen has a sticker or other obstruction encroaching by more than $10\mbox{mm}$

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

MOT #1 2014-06-07 09:16

MOT test number 476718154124

Result ✓ Passed

Advice Front registration plate delaminated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MAZDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

SM11MWY

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MAZDA had different number plates.

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-07-14
Last registration	2024-01-17
Complete history	See info



Registration #1	2011-07-14	10 mi
Registration #2	2014-06-07	23.206 mi
Registration #3	2015-09-30	39.555 mi
Registration #4	2015-09-30	39.555 mi
Registration #5	2016-09-29	54.418 mi
Registration #6	2017-09-26	65.502 mi
Registration #7	2018-09-27	76.788 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 ms
Registration #12		11.777 es
Registration #13		0.777 no

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4480 mm
Wheel base	2640 mm
Kerb weight	1332 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	Z6 938262

CarCheck.co.uk page 12/12