



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SE
Colour	Red
Year of manufacture	2015
Top speed	100 mph
0 - 100 km/h	14.3 seconds
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	44 kW / 60 HP / 59 BHP
Max. torque	95 Nm at 3.000 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	106 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-08-30
Pictures	39
Listing price	<a href="#">View report</a>



source: yesauto.com

**MOT history**

<b>MOT expiry date</b>	2025-02-21
<b>MOT pass rate</b>	86 %
<b>MOT passed</b>	6
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	9
<b>Total items failed</b>	1

<b>MOT #7</b>	2024-02-22 12:39
<b>MOT test number</b>	899081604366
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-02-21
<b>Advice</b>	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

<b>MOT #6</b>	2023-01-16 10:48
<b>MOT test number</b>	766615714223
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
<b>Advice</b>	Offside Rear Nail in tyre

<b>MOT #5</b>	2021-07-21 13:35
<b>MOT test number</b>	559869417855
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2020-07-24 16:00
<b>MOT test number</b>	925859677189
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3** 2020-07-24 14:15**MOT test number** 253093218823**Result** ✗ Failed**Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2019-08-30 08:27**MOT test number** 106881004426**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #1** 2018-09-15 15:17**MOT test number** 357571781189**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 March 2024

✓

MOT

Expires:  
21 February 2025

Tax status	Expired at 1 March 2024
Days left	59 days too late
MOT expiry date	21 February 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-09-21
Last registration	2024-02-22
Complete history	<a href="#">See info</a>



Registration #1	2015-09-21	15 mi
Registration #2	2018-09-15	18.945 mi
Registration #3	2019-08-30	27.977 mi
Registration #4	2020-07-24	32.621 mi
Registration #5	2020-07-24	32.622 mi
Registration #6	2020-07-24	32.622 mi
Registration #7	2020-07-24	32.622 mi
Registration #8	2020-07-24	32.622 mi
Registration #9	2020-07-24	32.622 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1682 mm
Height	1453 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CHYA451626