



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 XC70 D5 AWD SE EU4
Colour	Grey
Year of manufacture	2006
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-06-20
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-04
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2022-05-16
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	44
Total items failed	8

MOT #19	2021-05-17 13:01
MOT test number	708859790803
Result	✓ Passed
Next expiry date	2022-05-16
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #18	2020-07-10 11:42
MOT test number	556514421117
Result	✓ Passed
<b>Advice</b>	Front Suspension arm pin or bush worn but not resulting in excessive movement both sides starting to perish and split (5.3.4 (a) (i))
<b>Advice</b>	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #17	2020-07-08 10:28
MOT test number	994323780658
Result	✗ Failed
<b>MAJOR</b>	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
<b>Advice</b>	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
<b>Advice</b>	Front Suspension arm pin or bush worn but not resulting in excessive movement both sides starting to perish and split (5.3.4 (a) (i))
<b>MAJOR</b>	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #16**

2019-06-11 10:29

**MOT test number**

518673318723

**Result**

✓ Passed

- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement Front (5.3.4 (a) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #15**

2018-06-14 13:04

**MOT test number**

575818091589

**Result**

✓ Passed

**MOT #14**

2017-06-28 13:20

**MOT test number**

649648591594

**Result**

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)
- Advice** Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**MOT #13**

2017-06-26 10:48

**MOT test number**

682087591718

**Result****✗ Failed**

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Fail** Offside Front Outer Front position lamp(s) not working (1.1.A.3b)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front (2.4.G.2)

**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Fail** Nearside Front Outer Front position lamp(s) not working (1.1.A.3b)

**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement front (2.4.G.2)

**MOT #12**

2016-06-08 10:01

**MOT test number**

494828481860

**Result****✓ Passed**

**Advice** Offside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Child Seat fitted not allowing full inspection of adult belt X2

**MOT #11**

2015-08-27 12:43

**MOT test number**

736409863387

**Result****✓ Passed**

**MOT #10**

2014-08-18 11:00

**MOT test number**

337240834497

**Result**

✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front brake discs poor**MOT #9**

2013-08-13 15:55

**MOT test number**

377805923219

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Oil leak**MOT #8**

2013-08-13 13:11

**MOT test number**

645255923296

**Result**

✗ Failed

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak

**MOT #7** 2012-09-06 15:42**MOT test number** 356760952258**Result** ✓ Passed**MOT #6** 2012-04-17 10:41**MOT test number** 829428402113**Result** ✓ Passed**MOT #5** 2012-04-17 09:58**MOT test number** 316098802126**Result** ✗ Failed**Notice** Offside front wiper blade split**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2011-04-04 09:47**MOT test number** 777064291001**Result** ✓ Passed**MOT #3** 2010-04-15 12:08**MOT test number** 372095400156**Result** ✓ Passed**Notice** Nearside rear LED marker lights not working.**Notice** Brake pipe securing clips missing but brake pipes are not insecure.**Notice** All wheel drive not working (no drive to rear wheels).**MOT #2** 2009-04-15 08:38**MOT test number** 420255409144**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)



MOT #12009-04-15 08:38

MOT test number452245609120

Result

Failed

Pass with rectification

Offside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)

Advice

Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)





Tax & MOT check

✕  
Untaxed

Tax expired:  
11 May 2021

✕  
MOT

Expired:  
16 May 2022

Tax status	Expired at 11 May 2021
Days left	1084 days too late
MOT expiry date	16 May 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-20
Current registration	*****
Plate since	2019-06-20

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-04-28
Last registration	2021-05-17
Complete history	<a href="#">See info</a>



Registration #1	2006-04-28	26 mi
Registration #2	2009-04-15	18.031 mi
Registration #3	2010-04-15	20.574 mi
Registration #4	2011-04-04	22.390 mi
Registration #5	2012-04-17	23.991 mi
Registration #6	2012-04-17	23.991 mi
Registration #7	2012-09-06	24.904 mi
Registration #8	2013-08-13	35.635 mi
Registration #9	2013-08-13	35.365 mi
Registration #10	2014-08-18	45.647 mi
Registration #11	2015-08-27	51.490 mi
Registration #12	2016-05-20	55.277 mi
Registration #13	2016-05-20	55.277 mi
Registration #14	2016-05-20	55.277 mi
Registration #15	2016-05-20	55.277 mi
Registration #16	2016-05-20	55.277 mi
Registration #17	2016-05-20	55.277 mi
Registration #18	2016-05-20	55.277 mi
Registration #19	2016-05-20	55.277 mi
Registration #20	2016-05-20	55.277 mi
Registration #21	2016-05-20	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2100 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1719 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	363695