





report date: 2024-03-28

# General information

| Make                | CITROEN                    |
|---------------------|----------------------------|
| Model               | C3 AIRCROSS PURETECH FLAIR |
| Colour              | White                      |
| Year of manufacture | 2019                       |
| Top speed           | 100 mph                    |
| Gearbox             | 5 speed Manual             |

# Engine & fuel consumption

| Power                | 82 BHP              |
|----------------------|---------------------|
| Max. torque          | 118 Nm at 2.750 rpm |
| Engine capacity      | 1.199 сс            |
| Cylinders            | 3                   |
| Fuel type            | Petrol              |
| Consumption combined | 44.8 mpg            |
| CO2 emission         | 118 g/km            |
| CO2 label            | С                   |



CarCheck.co.uk page 1/10



report date: 2024-03-28


# Internet history

# Entry 1

Date 2021-09-03

Pictures 19

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/10



BP19DXG
report date: 2024-03-28

MOT history

| MOT expiry date    | 2025-03-07 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 3          |
| Failed MOT tests   | 0          |
| Total advice items | 8          |
| Total items failed | 0          |

| MOT #3    |   | 2024-02-14 15:01         |
|-----------|---|--------------------------|
| MOT test  | number  | 607133925983             |
| Result    |   | ✓ Passed                 |
| Next expi | ry date   | 2025-03-07               |
| Advice    | Nearside Front Brake disc worn, pitted or scored, but not seriously wea                           | akened (1.1.14 (a) (ii)) |
| Advice    | dvice Nearside Front Tyre worn close to legal limit/worn on edge 2mm worn outer edge (5.2.3 (e))  |                          |
| Advice    | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))                        |                          |
| Advice    | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))                         |                          |
| Advice    | dvice Offside Front Tyre worn close to legal limit/worn on edge 2.5mm worn outer edge (5.2.3 (e)) |                          |
| Advice    | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (                           | (ii))                    |
| Advice    | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i                           | ii))                     |

| MOT #2  | 2023-03-08 08:56 |
|---|------------------|
| MOT test number   | 390700017153     |
| Result  | <b>✓</b> Passed  |
|   |                  |
| MOT #1  | 2022-05-23 13:36 |
| MOT test number   | 119626751565     |
| Result  | ✓ Passed         |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt |                  |

CarCheck.co.uk page 3/10



report date: 2024-03-28

# Tax & MOT check



| Tax status       | Valid until 1 March |
|------------------|---------------------|
| Days left        | 306                 |
| MOT expiry date  | 7 March 2025        |
| Full MOT history | See MOT history     |

# Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | G          |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |

CarCheck.co.uk page 4/10



report date: 2024-03-28

### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



factor scincol

**BP19DXG** 

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this CITROEN had different number plates.

CarCheck.co.uk page 7/10



report date: 2024-03-28

### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 8/10



BP19DXG
report date: 2024-03-28

Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 5          |
| First mileage registration | 2019-06-11 |
| Last registration          | 2024-02-14 |
| Complete history           | See info   |



| Registration #1 | 2019-06-11 | 26 mi     |
|-----------------|------------|-----------|
| Registration #2 |            | 71.777 ea |
| Registration #3 | 2022-05-23 | 3.617 mi  |
| Registration #4 |            | 11.777 es |
| Registration #5 |            | 11,177 ms |

More info >

CarCheck.co.uk page 9/10



BP19DXG report date: 2024-03-28

Safety ratings

| NCAP rating    | ****            |  |
|----------------|-----------------|--|
| Adult          | 85%             |  |
| Children       | 82%             |  |
| Pedestrian     | 64%             |  |
| Safety systems | 60%             |  |
| Overall rating | 75%             |  |
| Video          | see crash video |  |

Dimensions & weight

| Width               | 1765 mm |
|---------------------|---------|
| Height              | 1637 mm |
| Length              | 4154 mm |
| Max. allowed weight | 1720 kg |

# Additional information

| Number of seats | 5           |
|-----------------|-------------|
| Number of axles | 2           |
| Engine number   | XKDN0031748 |

CarCheck.co.uk page 10/10