





General information

Make	FIAT
Model	PUNTO EVO DYNAMIC DUALOGIC
Colour	Grey
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	5.1 mpg
CO2 emission	124 g/km
CO2 label	D







Internet history

Entry 1	
Date	2021-01-29
Pictures	10
Listing price	<u>View report</u>









source: autoonline.co.uk



MOT history

MOT expiry date	2024-07-07
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	33
Total items failed	4

MOT #14	2023-06-12 11:13
MOT test number	706304367819
Result	🗸 Passed
Next expiry date	2024-07-07
Advice Rear exhaust box deteriorated	

MOT #13		2022-07-08 07:42
MOT test	number	891041967533
Result		✓ Passed
Advice	Rear springs corroded	
Advice	Oil leak	
Advice	Exhaust corroded	

MOT #12		2021-08-04 13:35
MOT test	number	305177069361
Result		✓ Passed
Advice	Rear Coil spring corroded NEARSIDE AND OFFSIDE (5.3.1 (b) (i))	
Advice Rear Exhaust has a minor leak of exhaust gases BACK BOX ALSO IS CORRODED (6.1.2 (a))		





MOT #11	2021-08-04 13:35	
MOT test number	623999314989	
Result	× Failed	
Advice Rear Coil spring corroded NEARSIDE AND OFFSIDE (5.3.1 (b) (i))		
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Rear Exhaust has a minor leak of exhaust gases BACK BOX ALSO IS CORRODED (6.1.2 (a))		

MOT #10		2020-08-13 10:47
MOT test	number	498849928616
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

МОТ #9	2020-08-13 10:47
MOT test number	836123159400
Result	🗙 Failed
Pass with rectification Offside Headlamp aim too far to the left (4.1.2 (a))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #8	2019-09-23 15:21
MOT test number	370890015308
Result	✓ Passed



MOT #7		2019-01-03 09:40
MOT test	number	970394539472
Result		✓ Passed
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))	
Advice reduced ch	Nearside Rear Integral body structure is deformed but structural rigidity is no nassis rail damaged (6.1.1 (a) (i))	ot significantly
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice reduced si	Nearside Outer Integral body structure is deformed but structural rigidity is r ll damaged (6.1.1 (a) (i))	not significantly

МОТ #6	2018-01-12 12:58
MOT test number	448813056982
Result	✓ Passed
Advice Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)	

MOT #5		2016-12-29 11:25
MOT test	number	610623967202
Result		✓ Passed
Advice	NSF tyre cracked and perished	
Advice	NSF outer parking lamp inoperative	
Advice	Front pads wearing thin	

HY11WFD

report date: 2024-03-28





MOT #42016-01-04 13:19MOT test number399781940275ResultPassedAdviceOSF tyre cracked and perishedAdviceOSR tyre cracked and perishedAdviceReversing sensor faultyAdviceNSF tyre cracked and perished

MOT #3		2016-01-04 13:19
MOT test number		149543824574
Result		🗙 Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice OSF tyre cracke	d and perished	
Advice OSR tyre cracke	d and perished	
Advice Reversing sense	or faulty	
Pass with rectification	Body has a projection caused by damage both front wheel trim	s (6.1.C.1)
Advice NSF tyre cracke	d and perished	

MOT #2	2015-01-12 17:30
MOT test number	555042515073
Result	✓ Passed

MOT #1	2014-01-14 10:27
MOT test number	498414714088
Result	✓ Passed



Tax & MOT check

Taxed Tax due: 1 February 2025	MOT Expires: 7 July 2024
Tax status	Valid until 1 February
Days left	279
MOT expiry date	7 July 2024
Full MOT history	<u>See MOT history</u>

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-24
Last registration	2023-06-12
Complete history	See info



Registration #1	2011-03-24	7 mi
Registration #2	2014-01-14	13.899 mi
Registration #3	2015-01-12	17.742 mi
Registration #4	2016-01-04	21.937 mi
Registration #5	2016-01-04	21.937 mi
Registration #6	2016-12-29	26.839 mi
Registration #7	2018-01-12	32.527 mi
Registration #8	2019-01-03	39.532 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	6234571