





report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO EXTREME 16V
Colour	Red
Year of manufacture	2010
Top speed	102 mph
0 - 60 mph	14.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	105 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	42.2 mpg
Consumption combined	33.2 mpg
CO2 emission	200 g/km
CO2 label	J



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2022-02-11

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

(b))

MOT expiry date	2024-06-02
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	7
Total items failed	10

MOT #14	2023-06-03 09:57
MOT test number	576105600259
Result	✓ Passed
Next expiry date	2024-06-02

MOT #13	2022-04-23 08:02
MOT test number	537399016030
Result	✓ Passed

MOT #12	2021-04-28 08:30
MOT test	number 404199021734
Result	✓ Passed
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4

MOT #11	2020-05-26 13:23
MOT test number	389594291187
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



Result

LX60DZC report date: 2024-03-29

✓ Passed

MOT #10 2019-05-08 14:07

MOT test number 321904323740

Result \rightarrow Passed

Advice Offside Front Tyre slight wear to outer edge.

MOT #9 2018-05-02 14:10

MOT test number 728529808166

Advice Offside Front Inner Road wheel slightly damaged rim (4.2.A.1a)

Advice Nearside Rear Tyre perished and cracked

MOT #8 2018-05-02 09:59

MOT test number 653414427204

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively Torn (8.2.2)

Advice Offside Front Inner Road wheel slightly damaged rim (4.2.A.1a)

Advice Nearside Rear Tyre perished and cracked

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively Torn (8.2.2)

Fail Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #7 2017-04-28 16:44

MOT test number 375215854202

Result ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #	6	2017-04-28 09:11
MOT te	est number	385235251183
Result		× Failed
Fail	Offside Front front brake binding (3.7.B.1)	
Fail	Offside rear brake binding (3.7.B.1)	
Fail	Nearside Front front brake binding (3.7.B.1)	
Fail	Exhaust has a major leak of exhaust gases (7.1.2)	
Fail	Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)	

MOT #5	2016-05-09 14:14
MOT test number	211086918022
Result	✓ Passed
MOT #4	2015-09-02 11:33
MOT test number	601703352023
Result	✓ Passed
MOT #3	2014-10-01 14:26
MOT test number	855704674284
Result	✓ Passed
MOT #2	2013-11-07 12:34
MOT test number	495321413497
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1

MOT test number

Result

Fail

Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)

Fail

Exhaust has a major leak of exhaust gases (7.1.2)

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	2 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

More info >

Owner history		
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		AULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	OK SIES	
Plate since		
Current registration	NK NE	
Plate since		

CarCheck.co.uk page 10/13



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-12-21
Last registration	2023-06-03
Complete history	See info



Registration #1	2010-12-21	27 mi
Registration #2	2013-10-28	21.531 mi
Registration #3	2013-11-07	21.531 mi
Registration #4	2014-10-01	27.104 mi
Registration #5	2015-09-02	33.052 mi
Registration #6	2016-05-09	34.810 mi
Registration #7	2017-04-28	39.023 mi
Registration #8	2017-04-28	39.042 mi
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.177 es
Registration #13		10.777 au
Registration #14		11.777 46
Registration #14 Registration #15		11.777 es

More info >

page 12/13 CarCheck.co.uk



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1829 mm
Height	1839 mm
Length	4213 mm
Wheel base	2697 mm
Max. allowed weight	1953 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

D003750