



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | V70 V70 170 SE |
| Colour | Green |
| Year of manufacture | 2002 |
| Top speed | 130 mph |
| 0 - 60 mph | 9.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 168 BHP |
| Max. torque | 230 Nm at 4.800 rpm |
| Engine capacity | 2.435 cc |
| Cylinders | 5 |
| Fuel type | Petrol |
| Consumption city | 23.0 mpg |
| Consumption extra urban | 40.9 mpg |
| Consumption combined | 31.7 mpg |
| CO2 emission | 219 g/km |
| CO2 label | K |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-06 |
| Pictures | 6 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2021-09-30 |
| MOT pass rate | 63 % |
| MOT passed | 15 |
| Failed MOT tests | 9 |
| Total advice items | 50 |
| Total items failed | 26 |

MOT #24 2020-09-30 14:54**MOT test number** 940627245995**Result** Passed**Next expiry date** 2021-09-30**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #23** 2019-10-01 13:55**MOT test number** 970675143778**Result** Passed**Advice** Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #22**

2019-09-27 10:06

MOT test number

888928835643

Result**✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear All direction indicators incorrect colour (4.4.3 (a))
- Advice** Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Offside Rear All direction indicators incorrect colour (4.4.3 (a))
- Fail** Offside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #21

2018-09-28 08:57

MOT test number

788765409282

Result**✓ Passed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #20**

2018-09-26 10:52

MOT test number

579712804553

Result**✗ Failed****Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Play in steering rack inner joint(s)**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))**MOT #19**

2017-09-30 10:46

MOT test number

685487742418

Result**✓ Passed****Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #18**

2017-09-30 10:18

MOT test number

793667736402

Result**✗ Failed****Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)



| | |
|-----------------|---|
| MOT #17 | 2016-11-05 11:45 |
| MOT test number | 251861096015 |
| Result | ✓ Passed |
| Advice | Offside Ball joint has slight play inner tie arm (2.2.B.1f) |
| Advice | Offside Rear binding slightly |

| | |
|-----------------|---|
| MOT #16 | 2015-10-01 10:10 |
| MOT test number | 713254277305 |
| Result | ✓ Passed |
| Advice | Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2) |
| Advice | Offside Rear coil spring corroded (2.4.C.1b) |
| Advice | Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a) |
| Advice | Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2) |
| Advice | Nearside Rear coil spring corroded (2.4.C.1b) |
| Advice | Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1) |

**MOT #15**

2015-10-01 10:10

MOT test number

675070900323

Result**✗ Failed**

- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Pass with rectification** Front position lamp(s) not working (1.1.A.3b)
- Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)
- Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)

MOT #14

2014-10-04 14:12

MOT test number

645477474215

Result**✓ Passed**

- Notice** Fuel filter corroded
- Advice** Power steering pump has slight seepage from a component (2.3.3b)
- Advice** Offside Ball joint has slight play (2.2.B.1f)
- Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

MOT #13

2013-10-02 10:47

MOT test number

995165273252

Result**✓ Passed**

- Notice** Rear tyre inner walls cracking

**MOT #12**

2013-10-02 10:02

MOT test number

306635873485

Result**✗ Failed****Notice** Rear tyre inner walls cracking**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #11**

2012-10-01 10:43

MOT test number

435385372200

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Play in steering rack inner joint(s)**Advice** Nearside Front Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #10**

2012-10-01 10:43

MOT test number

719595272254

Result**✗ Failed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Notice** Play in steering rack inner joint(s)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #9** 2011-10-01 10:57**MOT test number** 538634871238**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Ball joint has slight play (2.2.B.1f)**MOT #8** 2010-09-23 15:14**MOT test number** 773786160285**Result** ✓ Passed**MOT #7** 2010-09-20 14:17**MOT test number** 402003360222**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2009-09-21 11:09**MOT test number** 801424969238**Result** ✓ Passed**MOT #5** 2009-09-21 11:09**MOT test number** 293574469229**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2008-09-17 09:55**MOT test number** 734081068265**Result** ✓ Passed



| | |
|-------------------------|--|
| MOT #3 | 2008-09-17 09:55 |
| MOT test number | 270331168287 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Front position lamp(s) not working (1.1.A.3b) |

| | |
|-----------------|------------------|
| MOT #2 | 2007-09-24 14:28 |
| MOT test number | 803927467299 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2006-09-29 15:30 |
| MOT test number | 303552376295 |
| Result | ✓ Passed |



Tax & MOT check

✕
Untaxed

Tax expired:
1 September 2021

✕
MOT

Expired:
30 September 2021

| | |
|------------------|---------------------------------|
| Tax status | Expired at 1 September |
| Days left | 972 days too late |
| MOT expiry date | 30 September 2021 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 23 |
| First mileage registration | 2002-09-27 |
| Last registration | 2020-09-30 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2002-09-27 | 15 mi |
| Registration #2 | 2006-09-29 | 49.920 mi |
| Registration #3 | 2007-09-24 | 57.463 mi |
| Registration #4 | 2008-09-17 | 64.019 mi |
| Registration #5 | 2009-09-21 | 73.607 mi |
| Registration #6 | 2010-09-20 | 82.457 mi |
| Registration #7 | 2010-09-23 | 82.457 mi |
| Registration #8 | 2011-10-01 | 89.736 mi |
| Registration #9 | 2012-10-01 | 99.314 mi |
| Registration #10 | 2013-10-02 | 108.523 mi |
| Registration #11 | 2013-10-02 | 108.523 mi |
| Registration #12 | 2014-10-04 | 118.377 mi |
| Registration #13 | 2015-10-05 | 128.231 mi |
| Registration #14 | 2016-10-06 | 138.085 mi |
| Registration #15 | 2017-10-07 | 147.939 mi |
| Registration #16 | 2018-10-08 | 157.793 mi |
| Registration #17 | 2019-10-09 | 167.647 mi |
| Registration #18 | 2020-09-30 | 177.501 mi |
| Registration #19 | 2020-09-30 | 177.501 mi |
| Registration #20 | 2020-09-30 | 177.501 mi |
| Registration #21 | 2020-09-30 | 177.501 mi |
| Registration #22 | 2020-09-30 | 177.501 mi |
| Registration #23 | 2020-09-30 | 177.501 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|-------------|---------|
| Width | 1760 mm |
| Height | 1410 mm |
| Length | 4720 mm |
| Wheel base | 2560 mm |
| Kerb weight | 1483 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of axles | 2 |
| Engine number | 2816159 |