




report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | JAGUAR |
| Model | S-TYPE V6 SE |
| Colour | Blue |
| Year of manufacture | 2006 |
| Top speed | 145 mph |
| 0 - 60 mph | 7.5 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 240 BHP |
| Max. torque | 299 Nm at 4.100 rpm |
| Engine capacity | 2.967 cc |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 18.5 mpg |
| Consumption extra urban | 35.3 mpg |
| Consumption combined | 26.4 mpg |
| CO2 emission | 259 g/km |
| CO2 label | M |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-18 |
| Pictures | 29 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-05-15 |
| MOT pass rate | 79 % |
| MOT passed | 15 |
| Failed MOT tests | 4 |
| Total advice items | 19 |
| Total items failed | 5 |

MOT #19 2023-05-11 15:17

MOT test number 469168742335

Result ✓ Passed

Next expiry date 2024-05-15

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has a slightly worn bush lower shock absorber bush slightly worn (5.3.2 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18 2022-05-07 10:10

MOT test number 761716285142

Result ✓ Passed

- Advice** Both front tyres void of tread on inner edges

MOT #17 2021-05-08 10:32

MOT test number 309483679302

Result ✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))

**MOT #16** 2021-05-08 10:32**MOT test number** 991198767988**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))**MOT #15** 2020-05-16 09:57**MOT test number** 193338232499**Result** ✓ Passed**MOT #14** 2019-04-14 11:36**MOT test number** 133810575825**Result** ✓ Passed**MOT #13** 2019-04-14 11:36**MOT test number** 836717746577**Result** ✗ Failed**Pass with rectification** Windscreen washer not working (3.5 (a))**Pass with rectification** Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**MOT #12** 2018-05-08 12:13**MOT test number** 852098734826**Result** ✓ Passed**MOT #11** 2017-05-12 09:32**MOT test number** 660274104606**Result** ✓ Passed

**MOT #10** 2016-05-13 12:49**MOT test number** 968130702806**Result** ✓ Passed**Advice** Offside Front Inner steering arm has slight play**Advice** Nearside Front Inner steering arm has slight play**MOT #9** 2015-05-15 09:16**MOT test number** 839765035178**Result** ✓ Passed**MOT #8** 2014-05-12 16:28**MOT test number** 217642334415**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-05-12 15:15**MOT test number** 189752734163**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front registration plate delaminated (6.3.1d)**MOT #6** 2013-05-13 09:32**MOT test number** 606953233131**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Oil leak

**MOT #5** 2012-05-15 09:16**MOT test number** 395116132117**Result** ✓ Passed**MOT #4** 2011-05-05 12:37**MOT test number** 427325421192**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-05-11 09:29**MOT test number** 362851730166**Result** ✓ Passed**MOT #2** 2009-05-07 15:44**MOT test number** 694927729113**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Rear number plate has slight water damage**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2009-05-06 09:58**MOT test number** 742216729194**Result** ✗ Failed**Fail** Nearside Inner Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Rear number plate has slight water damage**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
15 May 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 124 |
| MOT expiry date | 15 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | M |
| Single payment (12 months) | £ 695,00,- |
| Single six month payment | £ 382,25,- |
| Total payable by 12 monthly instalments | £ 729,75,- |



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

| | |
|----------|--|
| Damage 1 | |
| Date | |
| Category | |
| Type | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2006-05-19 |
| Last registration | 2023-05-11 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-05-19 | 8 mi |
| Registration #2 | 2009-05-06 | 14.334 mi |
| Registration #3 | 2009-05-07 | 14.337 mi |
| Registration #4 | 2010-05-11 | 19.810 mi |
| Registration #5 | 2011-05-05 | 26.812 mi |
| Registration #6 | 2012-05-15 | 36.976 mi |
| Registration #7 | 2013-05-13 | 45.371 mi |
| Registration #8 | 2014-05-12 | 52.969 mi |
| Registration #9 | 2014-05-12 | 52.969 mi |
| Registration #10 | 2015-05-15 | 60.521 mi |
| Registration #11 | 2016-05-13 | 67.052 mi |
| Registration #12 | 2016-05-13 | 67.052 mi |
| Registration #13 | 2016-05-13 | 67.052 mi |
| Registration #14 | 2016-05-13 | 67.052 mi |
| Registration #15 | 2016-05-13 | 67.052 mi |
| Registration #16 | 2016-05-13 | 67.052 mi |
| Registration #17 | 2016-05-13 | 67.052 mi |
| Registration #18 | 2016-05-13 | 67.052 mi |
| Registration #19 | 2016-05-13 | 67.052 mi |
| Registration #20 | 2016-05-13 | 67.052 mi |
| Registration #21 | 2016-05-13 | 67.052 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2040 mm |
| Height | 1444 mm |
| Length | 4861 mm |
| Wheel base | 2909 mm |
| Kerb weight | 1710 kg |
| Max. allowed weight | 2180 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 69 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 542328359FG |