



RENAULT

BJ6IPGZ

report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO ML20 DCI
Colour	White
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	16.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.900 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	54.3 mpg







Internet history

Entry 1

Date	2021-06-26
Pictures	31
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-06-28
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	36
Total items failed	1

MOT #14 2023-06-27 08:31**MOT test number** 438770006254**Result** Passed**Next expiry date** 2024-06-28

- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view small chips in swept area (3.2 (a) (i))

MOT #13 2022-06-29 14:21**MOT test number** 250948009584**Result** Passed

- Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #12** 2022-06-29 11:33**MOT test number** 133194056484**Result** ✗ Failed**DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #11** 2021-06-23 15:55**MOT test number** 225555990486**Result** ✓ Passed**MOT #10** 2020-10-02 12:26**MOT test number** 837845231126**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2020-10-02 12:26**MOT test number** 286824874351**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2019-09-09 11:22**MOT test number** 493813391155**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-09-03 13:27**MOT test number** 900866345500**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #6** 2018-09-15 09:57**MOT test number** 585614233045**Result** ✓ Passed**MOT #5** 2018-09-15 08:03**MOT test number** 642647147476**Result** ✗ Failed**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #4** 2017-08-25 09:20**MOT test number** 660279292920**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #3** 2016-07-14 14:50**MOT test number** 890753174828**Result** ✓ Passed**MOT #2** 2015-11-03 13:26**MOT test number** 339140353959**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Centre brake light not working**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nail in tyre o/s/r**MOT #1** 2014-11-28 12:27**MOT test number** 486102434406**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
28 June 2024

Tax status	Valid until 1 June
-------------------	--------------------

Days left	34
------------------	----

MOT expiry date	28 June 2024
------------------------	--------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	BJ61PGZ
Plate since	2024-03-29
Current registration	BJ61PGZ
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-11-30
Last registration	2023-06-27
Complete history	See info



Registration #1	2011-11-30	11 mi
Registration #2	2014-11-28	24.606 mi
Registration #3	2015-11-03	32.786 mi
Registration #4	2016-07-14	33.075 mi
Registration #5	2017-08-25	43.208 mi
Registration #6	2018-09-15	64.781 mi
Registration #7	2018-09-15	64.781 mi
Registration #8	2019-09-03	91.228 mi
Registration #9	2019-09-03	91.228 mi
Registration #10	2019-09-03	91.228 mi
Registration #11	2019-09-03	91.228 mi
Registration #12	2019-09-03	91.228 mi
Registration #13	2019-09-03	91.228 mi
Registration #14	2019-09-03	91.228 mi
Registration #15	2019-09-03	91.228 mi
Registration #16	2019-09-03	91.228 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2133 mm
Height	1844 mm
Length	4213 mm
Kerb weight	1268 kg
Max. allowed weight	2077 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	D194696