



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 S
Colour	Silver
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-06
Pictures	11
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #19	2021-07-08 16:24
MOT test number	781011730343
Result	✓ Passed
Next expiry date	2022-07-07

MOT #18	2020-11-28 12:31
MOT test number	500790812190
Result	✓ Passed

Advice Parking brake lever has little reserve travel close to excessive

Advice Rear exhaust hanger broken

MOT #17	2020-11-28 09:59
MOT test number	350799998731
Result	✗ Failed

Advice Parking brake lever has little reserve travel close to excessive

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front tyre worn heavily on edges

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Nail in tyre and worn heavily on edges

Advice Rear exhaust hanger broken

MOT #16	2019-05-14 15:31
MOT test number	140848621367
Result	✓ Passed

Advice Power steering rack and pipes damp



MOT #15	2019-05-14 15:31
MOT test number	926064068968
Result	✗ Failed
Pass with rectification	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Power steering rack and pipes damp

MOT #14	2018-05-17 11:17
MOT test number	764939705615
Result	✓ Passed

MOT #13	2017-05-18 14:28
MOT test number	603507843798
Result	✓ Passed
Advice	Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #12	2017-05-18 14:28
MOT test number	436666651739
Result	✗ Failed
Advice	Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
Pass with rectification	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Offside Front Direction indicator incorrect colour (1.4.A.2f)

MOT #11	2016-05-23 14:05
MOT test number	783352155458
Result	✓ Passed
Advice	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #10	2014-05-30 09:35
----------------	------------------

MOT test number	305430354184
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2013-06-05 16:15
---------------	------------------

MOT test number	348156853142
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2012-12-14 09:45
---------------	------------------

MOT test number	467869942391
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2011-12-16 12:39
---------------	------------------

MOT test number	866300051353
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2011-01-21 11:29
---------------	------------------

MOT test number	258671121076
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2010-01-22 11:39
---------------	------------------

MOT test number	830372420087
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-03-25 12:50
---------------	------------------

MOT test number	912884589026
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #3	2009-03-25 11:45
MOT test number	414554289093
Result	✗ Failed
Advice	Nearside Front brake disc slightly pitted (3.5.1h)
Fail	Offside Front brake disc excessively pitted (3.5.1h)

MOT #2	2008-03-28 14:59
MOT test number	733798188088
Result	✓ Passed

MOT #1	2007-03-07 16:39
MOT test number	794166767063
Result	✓ Passed




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	GY04YXN
Plate since	2019-03-29
Current registration	GY04YXN
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-03-31
Last registration	2021-07-08
Complete history	See info



Registration #1	2004-03-31	27 mi
Registration #2	2007-03-07	17.131 mi
Registration #3	2008-03-28	21.078 mi
Registration #4	2009-03-25	24.687 mi
Registration #5	2009-03-25	24.687 mi
Registration #6	2010-01-22	27.001 mi
Registration #7	2011-01-21	27.104 mi
Registration #8	2011-12-16	29.215 mi
Registration #9	2012-12-14	32.055 mi
Registration #10	2013-06-05	32.788 mi
Registration #11	2014-05-30	36.435 mi
Registration #12	2015-05-20	35.377 mi
Registration #13	2016-05-20	35.377 mi
Registration #14	2017-05-20	35.377 mi
Registration #15	2018-05-20	35.377 mi
Registration #16	2019-05-20	35.377 mi
Registration #17	2020-05-20	35.377 mi
Registration #18	2021-05-20	35.377 mi
Registration #19	2022-05-20	35.377 mi
Registration #20	2023-05-20	35.377 mi
Registration #21	2024-05-20	35.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1720 mm
Height	1400 mm
Length	4520 mm
Wheel base	2560 mm
Kerb weight	1427 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	174526