



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT SRI
Colour	Turquoise
Year of manufacture	2008
Top speed	130 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	175 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H






Internet history

Entry 1

Date	2022-02-11
Pictures	6
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-21
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	19
Total items failed	18

MOT #24	2024-02-15 17:02
MOT test number	750797065185
Result	✓ Passed
Next expiry date	2025-02-21

MOT #23	2024-02-13 12:42
MOT test number	314514134004
Result	✗ Failed
Fail	Emissions unable to be completed due to large exhaust blow (8.2.1.2 (d))
Fail	Nearside Front Outer Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #22	2023-02-22 13:47
MOT test number	281684830040
Result	✓ Passed
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i))

**MOT #21**

2023-02-20 17:29

MOT test number

530525938004

Result**✗ Failed****Fail** Offside Front Outer Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #20**

2022-02-18 15:34

MOT test number

469418020237

Result**✓ Passed****Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**MOT #19**

2022-02-17 12:46

MOT test number

647635753480

Result**✗ Failed****Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #18** 2021-03-19 09:06**MOT test number** 130178122687**Result** ✓ Passed**MOT #17** 2020-03-18 12:08**MOT test number** 209849415136**Result** ✓ Passed**MOT #16** 2020-03-18 09:28**MOT test number** 542230844697**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Rear Brake pad(s) incorrectly mounted (1.1.13 (c))**MOT #15** 2019-03-21 11:26**MOT test number** 463131107910**Result** ✓ Passed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #14** 2018-03-19 09:53**MOT test number** 919552026838**Result** ✓ Passed**MOT #13** 2017-03-21 10:10**MOT test number** 355573796585**Result** ✓ Passed

**MOT #12** 2016-04-01 10:22**MOT test number** 915212498735**Result** ✓ Passed**MOT #11** 2015-03-16 07:42**MOT test number** 145025975017**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2015-03-16 07:42**MOT test number** 246025775082**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2015-02-13 11:32**MOT test number** 376864245007**Result** ✓ Passed**MOT #8** 2015-02-13 11:32**MOT test number** 808114545013**Result** ✗ Failed**Pass with rectification** Front Exhaust has a major leak of exhaust gases (7.1.2)**Pass with rectification** Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition (7.1.4)

**MOT #7** 2014-03-03 09:11**MOT test number** 179622264087**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2014-02-26 09:59**MOT test number** 935757354053**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2013-02-20 11:11**MOT test number** 417671353056**Result** ✓ Passed**MOT #4** 2013-02-15 10:48**MOT test number** 436916743025**Result** ✗ Failed**Fail** Offside Rear coil spring fractured (2.4.C.1a)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #3** 2012-02-14 10:24**MOT test number** 537685742089**Result** ✓ Passed**MOT #2** 2011-02-17 17:34**MOT test number** 616028341054**Result** ✓ Passed



MOT #1	2011-02-17 15:18
MOT test number	159798041011
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
21 February 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2008-03-04
Last registration	2024-02-15
Complete history	See info



Registration #1	2008-03-04	13 mi
Registration #2	2011-02-17	27.359 mi
Registration #3	2011-02-17	27.359 mi
Registration #4	2012-02-14	38.552 mi
Registration #5	2013-02-15	42.653 mi
Registration #6	2013-02-20	42.654 mi
Registration #7	2014-02-26	46.692 mi
Registration #8	2014-03-03	46.700 mi
Registration #9	2015-02-13	49.919 mi
Registration #10	2015-03-16	50.228 mi
Registration #11	2016-04-01	58.747 mi
Registration #12	2017-03-21	59.928 mi
Registration #13	2018-03-20	59.928 mi
Registration #14	2018-03-20	59.928 mi
Registration #15	2018-03-20	59.928 mi
Registration #16	2018-03-20	59.928 mi
Registration #17	2018-03-20	59.928 mi
Registration #18	2018-03-20	59.928 mi
Registration #19	2018-03-20	59.928 mi
Registration #20	2018-03-20	59.928 mi
Registration #21	2018-03-20	59.928 mi
Registration #22	2018-03-20	59.928 mi
Registration #23	2018-03-20	59.928 mi
Registration #24	2018-03-20	59.928 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	20LK4165