





report date: 2024-03-28

#### General information

Make	KIA
Model	CEED CRDI 1
Colour	Black
Year of manufacture	2014
Top speed	106 mph
0 - 60 mph	13.0 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 2.750 rpm
Engine capacity	1.396 сс
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date 2021-06-18

Pictures 28

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-29
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	25
Total items failed	4

MOT #11		2023-06-30 12:07
MOT test	number	251692461387
Result		<b>✓</b> Passed
Next expi	ry date	2024-06-29
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front both sides top strut mountings bearings slightly rough	
Advice	Front Play in steering rack inner joint(s) both sides	
<b>Advice</b> arm bush	Nearside Rear Suspension arm pin or bush worn but not resulting in exce (5.3.4 (a) (i))	essive movement trailing
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Lower Suspension arm corroded but not seriously weakened both si	des (5.3.3 (b) (i))
<b>Advice</b> arm bush	Offside Rear Suspension arm pin or bush worn but not resulting in excess (5.3.4 (a) (i))	sive movement trailing

CarCheck.co.uk page 3/13



MOT #10 2023-06-30 08:24

**MOT test number** 588408949454

**Result** X Failed

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Advice Rear Lower Suspension arm corroded but not seriously weakened both sides (5.3.3 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MAJOR Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**Advice** Front both sides top strut mountings bearings slightly rough

**Advice** Front Play in steering rack inner joint(s) both sides

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #9 2022-06-24 08:58

**MOT test number** 378564149889

**Result** ✓ Passed

**MOT #8** 2021-06-22 13:16

**MOT test number** 955398967548

**Result** 
✓ Passed

**MOT #7** 2021-03-02 10:44

**MOT test number** 325470638868

Result \rightarrow Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



MOT #6 2020-02-27 10:31

MOT test number 267450684132

**Result** ✓ Passed

**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #5** 2019-03-01 10:42

**MOT test number** 812623537890

Result \( \sqrt{Passed} \)

**MOT #4** 2018-02-27 15:03

**MOT test number** 610258070065

**Advice** Offside Front Tyre worn close to the legal limit edge (4.1.E.1)

**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #3 2018-02-27 09:52

**MOT test number** 753628179211

**Result** X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit edge (4.1.E.1)

**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #2 2017-03-03 15:36

**MOT test number** 325027925168

**Result** 
✓ Passed

CarCheck.co.uk page 5/13



MOT #1 2017-03-03 11:27

MOT test number 667093103111

Result

**X** Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 6/13



#### Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	29 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

•		
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report I		
*********		
***************************************		
***************************************		
	More info	>
Plate changes  See in this check if this KIA had different number plates.		
See in this cheek if this KiA had different number places.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	OK SIES	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



#### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-05
Last registration	2023-06-30
Complete history	See info



Registration #1	2014-03-05	17 mi
Registration #2	2017-03-03	29.618 mi
Registration #3	2017-03-03	29.618 mi
Registration #4	2018-02-27	39.963 mi
Registration #5	2018-02-27	39.963 mi
Registration #6	2019-03-01	49.660 mi
Registration #7	2020-02-27	60.089 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		70,777 mg

More info >

CarCheck.co.uk page 12/13



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	see crash video



## Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1489 kg
Max. allowed weight	1910 kg

# Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/1

Number of axles 2

**Engine number** D4FCEZ117617