






report date: 2024-03-28

### General information

Make	CITROEN	
Model	C4 CACTUS PURETECH FEEL S/S	
Colour	Blue	
Year of manufacture	2018	
Top speed	117 mph	
0 - 60 mph	9.3 seconds	
Gearbox	5 speed Manual	

## Engine & fuel consumption

Power	108 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	76.3 mpg
Consumption combined	65.7 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

### Entry 5

Date 2021-09-12

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

#### Entry 4

Date	2021-09-11
Date	2021-09-11

Pictures 45

Listing price <u>View report</u>









source: heycar.co.uk

Entry 3

Date 2021-08-16

Pictures 45

Listing price <u>View report</u>









source: heycar.co.uk

#### Entry 2

Pictures 16

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-07-15

Pictures 45

Listing price <u>View report</u>









source: cargurus.co.uk



YM18BRX report date: 2024-03-28

MOT history

MOT expiry date	2025-04-12
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	6
Total items failed	5

MOT #5	2024-04-12 14:54
MOT test number	586836393250
Result	✓ Passed
Next expiry date	2025-04-12
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #4	2024-04-12 10:27
MOT test number	870210881083
Result	<b>×</b> Failed
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii	))
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



YM18BRX report date: 2024-03-28

MOT #3 2023-04-06 10:24

**MOT test number** 890259811005

**Result** ✓ Passed

**Advice** Items removed from driver's view prior to test

Advice Front Brake disc worn, pitted or scored, but not seriously weakened n/s/f & o/s/f (1.1.14 (a) (ii))

MOT #2 2022-04-09 09:21

**MOT test number** 690711322694

Result \rightarrow Passed

MOT #1 2021-04-13 08:33

**MOT test number** 651389490632

Result \rightarrow Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	12 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NK SIK
Flate since	
Current registration	UK UK
Plate since	
	Moro info

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2018-06-29
Last registration	2024-04-12
Complete history	See info



Registration #1	2018-06-29	10 mi
Registration #2	2021-04-13	6.559 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 10/11



YM18BRX report date: 2024-03-28

Safety ratings

NCAP rating	***
Adult	82%
Children	79%
Pedestrian	80%
Safety systems	56%
Overall rating	76%
Video	see crash video

# Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1030 kg
Max. allowed weight	1565 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	XVA31087654

CarCheck.co.uk page 11/11