





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	JETTA SE TDI
Colour	Black
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg



CarCheck.co.uk page 1/10



2020-04-15 13:56

MOT history

MOT #11

MOT test number

Result

Next expiry date

124382544944

✓ Passed
2021-04-14

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Non obligatory mirror damaged

MOT #10 2020-04-15 13:56

MOT test number 805251964327

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Non obligatory mirror damaged

Pass with rectification Nearside Front Headlamp insecure (4.1.1 (c))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 2/10



MOT #9 2018-11-08 16:30

MOT test number 672322371289

Result ✓ Passed

Minor Nearside Rear Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2017-10-23 09:37

MOT test number 303550823139

Result ✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2016-10-04 10:15

MOT test number 349023768026

MOT #6 2015-09-29 10:39

MOT test number 280221384316

Result

Passed

MOT #5 2014-09-25 13:06

MOT test number 626638664285

Result ✓ Passed

MOT #4 2013-10-02 16:08

MOT test number 136885673294

Result
✓ Passed

CarCheck.co.uk page 3/10



MOT #3 2013-01-16 11:57
MOT test number 747786913006

MOT #2 2013-01-16 11:55

MOT test number 946176313044

Result X Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1 2012-07-21 11:51

MOT test number 699113702293

CarCheck.co.uk page 4/10




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type
Damage 2
Date



Туре

Category

Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

	More info >
Plate changes See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NY
Plate since	
Current registration	UK ZIK
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-09-23
Last registration	2020-04-15
Complete history	See info



Registration #1	2009-09-23	23 mi
Registration #2	2012-07-21	29.232 mi
Registration #3	2013-01-16	29.381 mi
Registration #4	2013-01-16	29.381 mi
Registration #5	2013-10-02	32.662 mi
Registration #6	2014-09-25	52.546 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11 .177 au

More info >

CarCheck.co.uk page 9/10



Car features

50225	Air conditionir
50295	
50482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1781 mm
Height	1459 mm
Length	4554 mm
Wheel base	2578 mm
Kerb weight	1508 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack co.uk	page 10/1

CarCheck.co.uk page 10/10

Number of seats	5
Number of axles	2
Engine number	BXEB69305