



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-07-16
Pictures	21
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-19
Pictures	10
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-02
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	30
Total items failed	13

MOT #16 2023-12-28 16:06

MOT test number 568711845234

Result ✓ Passed

Next expiry date 2025-01-02

- Advice** Engine covers/Under trays fitted
- Advice** Vehicle is Heavily Under-sealed.
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Under-chassis, Suspension, Exhaust & Brake components corroded.
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15 2022-12-27 14:35

MOT test number 460828371113

Result ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2021-12-21 17:31

MOT test number

235976258847

Result

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake pad(s) wearing thin Offside & Nearside (1.1.13 (a) (ii))
- Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin Offside & Nearside (1.1.13 (a) (ii))
- Advice** Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #13

2020-12-30 15:40

MOT test number

531915443689

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush perished. (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush perished (5.3.4 (a) (i))

**MOT #12**

2020-12-30 12:36

MOT test number

696055503887

Result**✗ Failed****Fail**

Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush perished. (5.3.4 (a) (i))

Advice

Offside Front Nail in tyre

Advice

Offside Front Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush perished (5.3.4 (a) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Minor

Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #11

2020-01-02 10:27

MOT test number

911400985166

Result**✓ Passed****MOT #10**

2019-12-17 10:19

MOT test number

100646459320

Result**✗ Failed****Fail**

Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail

Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

Fail

Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #9

2019-01-03 16:33

MOT test number

291979017245

Result**✓ Passed**

**MOT #8** 2018-02-27 14:56**MOT test number** 144985761418**Result** ✓ Passed**MOT #7** 2017-02-28 14:10**MOT test number** 406043417768**Result** ✓ Passed**MOT #6** 2016-02-19 10:37**MOT test number** 512363841678**Result** ✓ Passed**MOT #5** 2015-06-25 12:35**MOT test number** 985376175168**Result** ✓ Passed**MOT #4** 2015-06-25 09:36**MOT test number** 306706475174**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside Rear Anti-roll bar linkage rubber mounting deteriorated resulting in excessive movement (2.4.G.2)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside rear brake binding (3.7.B.1)



MOT #3	2014-06-19 10:57
MOT test number	309210774153
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #2	2014-06-19 10:57
MOT test number	936650574128
Result	✗ Failed
Pass with rectification	Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Pass with rectification	Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1	2013-06-26 11:47
MOT test number	209787173169
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
2 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	2 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YB10CGK
Plate since	2019-03-28
Current registration	YB10CGK
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-07-08
Last registration	2023-12-28
Complete history	See info



Registration #1	2010-07-08	23 mi
Registration #2	2013-06-26	39.567 mi
Registration #3	2014-06-19	51.063 mi
Registration #4	2015-06-25	64.188 mi
Registration #5	2015-06-25	64.188 mi
Registration #6	2016-02-19	68.611 mi
Registration #7	2017-02-28	77.453 mi
Registration #8	2018-02-27	85.345 mi
Registration #9	2019-01-03	89.341 mi
Registration #10	2019-01-03	89.341 mi
Registration #11	2019-01-03	89.341 mi
Registration #12	2019-01-03	89.341 mi
Registration #13	2019-01-03	89.341 mi
Registration #14	2019-01-03	89.341 mi
Registration #15	2019-01-03	89.341 mi
Registration #16	2019-01-03	89.341 mi
Registration #17	2019-01-03	89.341 mi
Registration #18	2019-01-03	89.341 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

AU21080