





report date: 2024-03-28

General information

Make	AUDI
Model	A3 TDI SPORT SPECIAL EDITION
Colour	Blue
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/14



MOT history

MOT expiry date	2025-04-24
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	45
Total items failed	8

MOT #18	2024-04-25 09:40	
MOT test number	348528844912	
Result	✓ Passed	
Next expiry date	2025-04-24	
Advice Nearside Front Lower Suspension arm ball joint has slight play lower ball joint (5.3.4 (a) (i)) Advice Front Suspension arm pin or bush worn but not resulting in excessive movement offside and		
nearside lower arm rear bushes (5.3.4 (a) (i))		
Advice Offside Front Outer Track rod end ball joint has slight play track rod end deteriorated (2.1.3 (b) (i))	nd has play and dust cover is	

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT #17 2024-04-16 12:47

MOT test number 318970105578

Result

× Failed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement offside and nearside lower arm rear bushes (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm ball joint has slight play lower ball joint (5.3.4 (a) (i))

Fail Offside Front Headlamp aim projected beam image is obviously incorrect beam pattern incorrect, possibly incorrect bulb type or not seated correctly (4.1.2 (c))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. offside is higher in effort by over 25% at mid braking point (1.2.1 (b) (i))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect beam pattern incorrect, possibly incorrect bulb type or not seated correctly (4.1.2 (c))

Advice Offside Front Outer Track rod end ball joint has slight play track rod end has play and dust cover is deteriorated (2.1.3 (b) (i))

Fail Nearside Rear Wheel bearing has excessive play excessive play and notchy when rotated (5.1.3 (a) (i))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #16 2023-03-22 10:59

MOT test number 743992869139

Result

✓ Passed

Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice

Offside Front Sub-frame ball joint has slight play (5.3.4 (a) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2021-03-15 17:07 **MOT** test number 726417435160 Result ✓ Passed **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (I))

MOT #13 2021-03-15 14:26 **MOT** test number 290385751547 Result × Failed **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

CarCheck.co.uk page 4/14



MOT test number

525373378238

Result

Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both sides rear (5.3.4 (a) (i))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #11		2019-04-08 09:44
MOT test	number	377351096236
Result		✓ Passed
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt	
Advice (a) (i))	Front Suspension arm pin or bush worn but not resulting in excessive moveme	nt both sides (5.3.4
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Under trays fitted	

MOT #10		2018-04-09 11:03
MOT test	number	503575992979
Result		✓ Passed
Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)		
Advice Under trays fitted obscuring some components on the underside		
Advice (2.4.G.2)	Suspension arm rubber bush deteriorated but not resulting in excessive r	movement n/s/f and o/s/f

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #9 2017-04-13 16:54

MOT test number 430158017768

Advice Under trays fitted obscuring some components on the underside

MOT #8 2017-04-13 09:26

MOT test number 124116628964

Result X Failed

Advice Under trays fitted obscuring some components on the underside

Fail Nearside Stop lamp not working (1.2.1b)

Fail Offside Front coil spring broken (2.4.C.1a)

MOT #7 2016-04-14 09:37

MOT test number 899874024560

Result \(\sqrt{Passed} \)

Advice Under trays fitted obscuring some components in the engine bay

Advice Engine covers fitted obscuring some components in the engine bay

MOT #6 2015-04-14 13:23

MOT test number 565774705187

Result

Passed

Advice Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Nearside Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #5		2014-03-22 16:37
MOT test	number	395881784043
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	

MOT #4	2013-03-29 13:47
MOT test number	539818383053
Result	✓ Passed
MOT #3	2012-03-30 16:05
MOT test number	335980892010
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components	

MOT #2	2012-02-06 12:03
MOT test number	568527232017
Result	✓ Passed
MOT #1	2011-01-28 15:30
MOT test number	827298621023
Result	✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Plate since

Plate since

KS57WKP

report date: 2024-03-28

POR 20.20

EXCLUSION

More info >

Owner history		
For how long did the current and previous owner(s) have this AUDI? How many owners dicheck it in the premium report and see all owner registrations. Download the full report h		ve?
2000000		

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	NIK NIK	THE

CarCheck.co.uk page 11/14



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-02-05
Last registration	2024-04-25
Complete history	See info



Registration #1	2008-02-05	17 mi
Registration #2	2011-01-28	76.043 mi
Registration #3	2012-02-06	93.153 mi
Registration #4	2012-03-30	94.411 mi
Registration #5	2013-03-29	100.068 mi
Registration #6	2014-03-22	109.605 mi
Registration #7	2015-04-14	120.153 mi
Registration #8	2016-04-14	128.283 mi
Registration #9	2017-04-13	134.883 mi
Registration #10	2017-04-13	134.884 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		
Registration " 10		

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1957 mm
Height	1423 mm
Length	4286 mm
Wheel base	2578 mm
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 14/14