



General information

Make	VOLKSWAGEN
Model	PASSAT R LINE TDI
Colour	Grey
Year of manufacture	2010
Top speed	119 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-17
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-14
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	18
Total items failed	8

MOT #16	2023-10-10 12:59
MOT test number	631990109031
Result	✓ Passed
Next expiry date	2024-10-14
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2022-09-26 10:33
MOT test number	530879403953
Result	✓ Passed

MOT #14	2022-09-26 10:33
MOT test number	252131180456
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))

**MOT #13** 2021-10-14 08:46**MOT test number** 901411465865**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2020-10-15 15:26**MOT test number** 344374638666**Result** ✓ Passed**Advice** Advise front discs lipped and corroded**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Advise offside rear sidelight has a section not working**Advice** Advise rear discs lipped and corroded**MOT #11** 2019-09-07 14:42**MOT test number** 700952411636**Result** ✓ Passed**Advice** Under trays fitted

**MOT #10** 2019-09-07 13:09**MOT test number** 981366471654**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Under trays fitted**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9** 2018-10-01 11:24**MOT test number** 430893821550**Result** ✓ Passed**Advice** Tyre slightly damaged/cracking or perishing All four tyres (5.2.3 (d) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #8** 2017-09-29 12:47**MOT test number** 323862086288**Result** ✓ Passed**Advice** Factory fitted engine safety speed limiter does not allow to test for diesel smoke test**MOT #7** 2017-09-29 12:01**MOT test number** 620989668831**Result** ✗ Failed**Advice** Factory fitted engine safety speed limiter does not allow to test for diesel smoke test**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #6** 2017-04-07 08:43**MOT test number** 114752834430**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-03-30 08:34**MOT test number** 770215134970**Result** ✓ Passed**MOT #4** 2015-02-27 15:57**MOT test number** 406798555003**Result** ✓ Passed**MOT #3** 2015-02-27 10:25**MOT test number** 616718855081**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**MOT #2** 2014-03-21 16:33**MOT test number** 139710484032**Result** ✓ Passed**MOT #1** 2013-03-15 11:10**MOT test number** 949224373029**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
14 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	14 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GJ10CYZ
Plate since	2019-03-28
Current registration	 GJ10CYZ
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-25
Last registration	2023-10-10
Complete history	See info



Registration #1	2010-03-25	19 mi
Registration #2	2013-03-15	28.133 mi
Registration #3	2014-03-21	37.273 mi
Registration #4	2015-02-27	47.237 mi
Registration #5	2015-02-27	47.237 mi
Registration #6	2016-03-30	57.075 mi
Registration #7	2017-04-07	62.231 mi
Registration #8	2017-09-29	65.992 mi
Registration #9	2017-09-29	65.992 mi
Registration #10	2018-03-29	65.992 mi
Registration #11	2018-03-29	65.992 mi
Registration #12	2018-03-29	65.992 mi
Registration #13	2018-03-29	65.992 mi
Registration #14	2018-03-29	65.992 mi
Registration #15	2018-03-29	65.992 mi
Registration #16	2018-03-29	65.992 mi
Registration #17	2018-03-29	65.992 mi
Registration #18	2023-10-10	65.992 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1435 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBD 371263