



TOYOTA

GW55LMO

report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA D-4D T SPIRIT
Colour	Grey
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	250 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg





Internet history

Entry 1

Date	2021-06-25
Pictures	6
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #18	2021-02-03 10:06
MOT test number	737228250080
Result	✓ Passed
Next expiry date	2022-02-02
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2021-02-03 10:06
MOT test number	961794542021
Result	✗ Failed
Pass with rectification	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2019-07-31 09:48
MOT test number	812224342994
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2019-07-31 09:48
MOT test number	413631829360
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #14** 2018-08-01 12:51**MOT test number** 753221234009**Result** ✓ Passed**MOT #13** 2017-07-21 11:41**MOT test number** 383994462253**Result** ✓ Passed

Advice Offside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #12 2017-07-11 15:44**MOT test number** 227783505049**Result** ✗ Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Nearside front brake binding (3.7.B.1)

Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

Advice Offside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #11 2016-07-20 10:52**MOT test number** 164678199379**Result** ✓ Passed

Advice Offside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #10**

2016-07-19 14:51

MOT test number

250900286958

Result**✗ Failed**

- Fail** Brake hydraulic reservoir fluid level below minimum level (3.6.G.1b)
- Fail** Brake pedal creeps down while the pedal is held under pressure (3.3.B.1a)
- Advice** Offside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Fail** Service brake: efficiency below requirements (3.7.B.7)
- Fail** Offside Rear Brake hose leaking (3.6.A.1)
- Fail** Offside Rear rear brake recording little or no effort (3.7.B.5a)
- Fail** Brake pedal has insufficient reserve movement (3.3.A.5)
- Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)

MOT #9

2015-07-27 09:43

MOT test number

758498005288

Result**✓ Passed**

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Offside rear tyre on 3mm
- Advice** Offside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #8

2014-08-01 16:24

MOT test number

879873314279

Result**✓ Passed**

**MOT #7** 2013-07-30 10:01**MOT test number** 349171613423**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** ENGINE UNDERTRAY LOOSE**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-07-17 12:41**MOT test number** 259999492101**Result** ✓ Passed**MOT #5** 2012-07-17 12:41**MOT test number** 719429292162**Result** ✗ Failed**Pass with rectification** Centre Stop lamp not working (1.2.1b)**MOT #4** 2011-02-11 12:36**MOT test number** 979892041027**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #3	2011-02-08 11:32
MOT test number	925029531033
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Fail	Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)
Fail	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #2	2010-02-05 12:12
MOT test number	923196430067
Result	✓ Passed

MOT #1	2009-02-06 10:13
MOT test number	524867239037
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-02-08
Last registration	2021-02-03
Complete history	See info



Registration #1	2006-02-08	12 mi
Registration #2	2009-02-06	38.576 mi
Registration #3	2010-02-05	46.600 mi
Registration #4	2011-02-08	52.818 mi
Registration #5	2011-02-11	52.841 mi
Registration #6	2012-07-17	61.825 mi
Registration #7	2013-07-30	68.354 mi
Registration #8	2014-08-01	75.596 mi
Registration #9	2015-07-27	84.013 mi
Registration #10	2016-07-19	92.723 mi
Registration #11	2016-07-19	92.723 mi
Registration #12	2016-07-19	92.723 mi
Registration #13	2016-07-19	92.723 mi
Registration #14	2016-07-19	92.723 mi
Registration #15	2016-07-19	92.723 mi
Registration #16	2016-07-19	92.723 mi
Registration #17	2016-07-19	92.723 mi
Registration #18	2016-07-19	92.723 mi
Registration #19	2016-07-19	92.723 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1345 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1CD0552443