





report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT
Colour	Red
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-06-16

Pictures 54

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-06-12
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	16
Total items failed	7

MOT #15	2023-06-13 15:42
MOT test number	141714775212
Result	✓ Passed
Next expiry date	2024-06-12
Minor Offside Front Drive shaft joint constant velocity boot severely dete	eriorated (6.1.7 (g) (i))

MOT #14	2023-05-20 13:04
MOT test number	970169818326
Result	× Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Minor Offside Front Outer Drive shaft joint constant velocity boot severely dete	riorated (6.1.7 (g) (i))
Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Fail Offside Rear Service brake excessively binding (1.2.1 (f))	

MOT #13		2022-04-26 15:39
MOT test	number	841615890912
Result		✓ Passed
Advice	Covers and shields fitted	
Advice	Exhaust shield rattle	
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7	(g) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12 2022-04-26 10:20

MOT test number 176519984491

Result X Failed

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Covers and shields fitted

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Exhaust shield rattle

MOT #11 2021-05-18 09:04

MOT test number 893685104552

Result

Passed

MOT #10 2020-08-04 13:42

MOT test number 786081033550

Result
✓ Passed

MOT #9 2020-08-04 13:28

MOT test number 761002473459

Result X Failed

Fail Offside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

Fail Offside Front Headlamp aim too high (4.1.2 (a))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

859966067938

Result

Advice Service brake binding but not excessively both rear (1.2.1 (f))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #7 2019-08-13 14:02 **MOT** test number 441786595315 Result **X** Failed Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Service brake binding but not excessively both rear (1.2.1 (f)) Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt both front outer (6.1.7 (g) (ii))

MOT #6	2018-08-16 13:35
MOT test number	620857808923
Result	✓ Passed
MOT #5	2017-08-23 15:12
MOT test number	132382230028
Result	✓ Passed
MOT #4	2016-11-17 10:59
MOT test number	903509413671
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #3	2015-11-17 08:51
MOT test number	457634586965
Result	✓ Passed
MOT #2	2014-09-08 14:44
MOT test number	455471654287
Result	✓ Passed
MOT #1	2013-03-09 13:55
MOT test number	198508063048
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	12 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when motorly	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NE ZIN
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-12
Last registration	2023-06-13
Complete history	See info



Registration #1	2009-09-12	7 mi
Registration #2	2013-03-09	6.533 mi
Registration #3	2014-09-08	7.803 mi
Registration #4	2015-11-17	8.243 mi
Registration #5	2016-11-17	14.329 mi
Registration #6	2017-08-23	17.343 mi
Registration #7	2018-08-16	24.278 mi
Registration #8	2019-08-13	31.994 mi
Registration #9	2019-08-21	32.186 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		D.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1728 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/1