



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | HONDA |
| Model | HR-V I-VTEC SE |
| Colour | Blue |
| Year of manufacture | 2016 |
| Top speed | 116 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 1 speed CVT |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 129 BHP |
| Max. torque | 155 Nm at 4.600 rpm |
| Engine capacity | 1.498 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 52.3 mpg |
| CO2 emission | 125 g/km |
| CO2 label | D |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-26 |
| Pictures | 5 |
| Listing price | View report |

VEHICLE IN STOCK

Currently being prepared
Call for details

HENDY



GARDY X

PAINT AND FABRIC
PROTECTION AVAILABLE WITH
THIS VEHICLE



£99

RESERVE THIS
CAR FOR £99





BOOK A
TEST DRIVE TODAY



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-09 |
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 0 |

| | |
|------------------|---|
| MOT #6 | 2023-07-11 13:28 |
| MOT test number | 296548957441 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-09 |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge 215/55R17 Y - Barum (5.2.3 (e)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge 215/55R17 Y - Barum (5.2.3 (e)) |

| | |
|-----------------|---|
| MOT #5 | 2023-07-03 11:18 |
| MOT test number | 474150195833 |
| Result | ✗ Failed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge 215/55R17 Y - Barum (5.2.3 (e)) |
| Advice | Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge 215/55R17 Y - Barum (5.2.3 (e)) |
| MAJOR | Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| MAJOR | Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) |

| | |
|-----------------|------------------|
| MOT #4 | 2022-08-10 08:50 |
| MOT test number | 252831663240 |
| Result | ✓ Passed |



| | |
|-----------------|------------------|
| MOT #3 | 2021-07-08 11:04 |
| MOT test number | 310755110803 |
| Result | ✓ Passed |
| MOT #2 | 2020-07-16 10:24 |
| MOT test number | 812811102884 |
| Result | ✓ Passed |
| MOT #1 | 2019-07-24 14:40 |
| MOT test number | 975595678823 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
9 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 185 |
| MOT expiry date | 9 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HONDA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | HX66RNN |
| Plate since | 2024-03-29 |
| Current registration | HX66RNN |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 8 |
| First mileage registration | 2016-09-01 |
| Last registration | 2023-07-11 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2016-09-01 | 14 mi |
| Registration #2 | 2019-07-24 | 11.256 mi |
| Registration #3 | 2020-07-16 | 14.742 mi |
| Registration #4 | 2021-07-08 | 15.623 mi |
| Registration #5 | 2022-07-08 | 16.504 mi |
| Registration #6 | 2023-07-11 | 17.385 mi |
| Registration #7 | 2024-03-29 | 18.266 mi |
| Registration #8 | 2024-03-29 | 19.147 mi |

More info >

**Safety ratings**

| | |
|-----------------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 86% |
| Children | 79% |
| Pedestrian | 72% |
| Safety systems | 71% |
| Overall rating | 79% |
| Video | see crash video |

**Dimensions & weight**

| | |
|----------------------------|---------|
| Width | 1772 mm |
| Height | 1605 mm |
| Length | 4294 mm |
| Wheel base | 2610 mm |
| Kerb weight | 1322 kg |
| Max. allowed weight | 1790 kg |

Additional information

| | |
|---------------------------|-----------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | L15B41011238 |