




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT EXECUTIVE TDI BLUEMOTION TECHN
Colour	Blue
Year of manufacture	2014
Top speed	132 mph
0 - 100 km/h	10.0 seconds
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-12
Pictures	26
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2025-04-08
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #10	2024-04-08 08:45
MOT test number	996408828323
Result	✓ Passed
Next expiry date	2025-04-08

MOT #9	2023-03-28 12:25
MOT test number	511723314863
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2022-04-09 11:43
MOT test number	692557166249
Result	✓ Passed
Advice	Emissions were tested and met but dsm could not read the reading

MOT #7	2022-04-09 08:45
MOT test number	985849208416
Result	✗ Failed
Fail	Offside Front Lower Suspension arm pin or bush excessively worn console bush (5.3.4 (a) (i))
Advice	Emissions were tested and met but dsm could not read the reading

**MOT #6** 2021-03-13 12:54**MOT test number** 195859359354**Result** ✓ Passed**MOT #5** 2020-03-21 09:11**MOT test number** 550211171357**Result** ✓ Passed**MOT #4** 2019-03-23 11:04**MOT test number** 182080691616**Result** ✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Upper Driver's door hinge deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #3 2018-03-24 12:18**MOT test number** 732249301247**Result** ✓ Passed

- Advice** Offside Rear tyre uneven tread wear inner tread area
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' chipped windscreen (8.3.1d)



MOT #2	2018-03-24 09:13
MOT test number	103758633822
Result	✗ Failed
Fail	Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure inner tread area (4.1.D.1b)
Advice	Offside Rear tyre uneven tread wear inner tread area
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' chipped windscreen (8.3.1d)

MOT #1	2017-03-27 14:49
MOT test number	400830756625
Result	✓ Passed
Advice	Both front tyres low



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
8 April 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 ML14XCA
Plate since	2024-03-29
Current registration	 ML14XCA
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-31
Last registration	2024-04-08
Complete history	See info



Registration #1	2014-03-31	8 mi
Registration #2	2017-03-27	58.287 mi
Registration #3	2018-03-24	81.901 mi
Registration #4	2018-03-24	81.901 mi
Registration #5	2019-03-23	95.968 mi
Registration #6	2020-03-21	106.399 mi
Registration #7	2020-03-21	106.399 mi
Registration #8	2020-03-21	106.399 mi
Registration #9	2020-03-21	106.399 mi
Registration #10	2020-03-21	106.399 mi
Registration #11	2020-03-21	106.399 mi
Registration #12	2020-03-21	106.399 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1516 mm
Length	4771 mm
Wheel base	2712 mm
Kerb weight	1471 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CFFBK74752