





General information

| Make | VAUXHALL |
|---------------------|-------------------------|
| Model | GRANDLAND SPORT NAV S/S |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 115 mph |
| 0 - 60 mph | 12.2 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 300 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 57.7 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 112 g/km |
| CO2 label | С |







Internet history


Entry 2

Date

Pictures

2023-12-12

8



source: g3remarketing.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-07-19 |
| Pictures | 10 |
| Listing price | View report |
| | |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-08-03 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 14 |
| Total items failed | 1 |

| MOT #5 | | 2023-07-31 09:59 |
|-----------|--|------------------|
| MOT test | number | 159403944982 |
| Result | | 🗸 Passed |
| Next expi | ry date | 2024-08-03 |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #4 | | 2022-07-25 08:32 |
|----------|---|------------------|
| MOT test | number | 727618364798 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread | (5.2.3 (d) (ii)) |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5 | .2.3 (d) (ii)) |
| Advice | Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| | | |





| MOT #3 | 2021-08-04 16:34 |
|--|------------------|
| MOT test number | 390126676107 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2021-08-04 11:01 |
| MOT test number | 535446106840 |
| Result | 🗙 Failed |
| Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) | |
| MOT #1 | 2021-04-21 13:15 |
| MOT test number | 242070515572 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Front wipers poor cleaning. | |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |



Tax & MOT check

| √ Taxed | √ МОТ |
|-----------------------------|---------------------------|
| Tax due: 1 November 2024 | Expires: 3 August 2024 |
| Tax status | Valid until 1 November |
| Days left | 186 |
| MOT expiry date | 3 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | FET A |
| Category | L AMP |
| Туре | |
| Damage 2 | AMPLE |
| Date | 4 |
| Category | AMPL |
| Туре | |

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******** | |
|---|-------------|
| | |
| | |
| ********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| | |
| Plate since | |





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-06-20 |
| Last registration | 2023-07-31 |
| Complete history | See info |



| Registration #1 | 2018-06-20 | 15 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-04-21 | 10.047 mi |
| Registration #3 | | 11.777 mi |
| Registration #4 | 2021-08-04 | 10.636 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 esi |

More info >





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 87% |
| Pedestrian | 63% |
| Safety systems | 60% |
| Overall rating | 76% |
| Video | see crash video |



| Dimensions & weight | |
|--|--------------------------|
| Width | 1811 mm |
| Height | 1630 mm |
| Length | 4477 mm |
| Wheel base | 2675 mm |
| Kerb weight | 1430 kg |
| Max. allowed weight | 2000 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 53 I |
| | 53 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |