




report date: 2024-03-29

General information

| | |
|---------------------|------------------------------|
| Make | CITROEN |
| Model | C3 BLUEHDI SELECTION PICASSO |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 111 mph |
| 0 - 60 mph | 13.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 98 BHP |
| Max. torque | 254 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 60.1 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 72.4 mpg |
| CO2 emission | 101 g/km |
| CO2 label | B |





Internet history

Entry 4

| | |
|---------------|-----------------------------|
| Date | 2022-12-29 |
| Pictures | 1 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 3

| | |
|---------------|-----------------------------|
| Date | 2022-02-19 |
| Pictures | 32 |
| Listing price | View report |



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-02-18 |
| Pictures | 32 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-10 |
| Pictures | 47 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-26 |
| MOT pass rate | 64 % |
| MOT passed | 7 |
| Failed MOT tests | 4 |
| Total advice items | 18 |
| Total items failed | 11 |

| | |
|------------------|---|
| MOT #11 | 2024-02-27 14:20 |
| MOT test number | 519799300175 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-26 |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Minor | Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing sidewall cracking (5.2.3 (d) (ii)) |
| Advice | Offside Front Macpherson strut mounting damaged but not seriously weakened bearing worn (5.3.3 (b) (i)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing sidewall damage (5.2.3 (d) (ii)) |

**MOT #10**

2024-02-21 10:04

MOT test number

496972586103

Result**✗ Failed**

Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing sidewall damage (5.2.3 (d) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Macpherson strut mounting damaged but not seriously weakened bearing worn (5.3.3 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing sidewall cracking (5.2.3 (d) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #9

2023-02-01 16:05

MOT test number

201208073089

Result**✓ Passed****MOT #8**

2022-02-21 09:35

MOT test number

530391527539

Result**✓ Passed****MOT #7**

2022-02-21 08:54

MOT test number

898723503247

Result**✗ Failed**

Fail Exhaust system insecure (6.1.2 (a))

MOT #6

2021-05-20 15:39

MOT test number

860712179449

Result**✓ Passed**

**MOT #5** 2021-05-20 13:31**MOT test number** 277591134339**Result** ✗ Failed

- Fail** Brake pad(s) less than 1.5 mm thick Both front (1.1.13 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Brake disc in such a condition that it is seriously weakened Both front (1.1.14 (a) (ii))
- Fail** Exhaust system insecure (6.1.2 (a))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #4 2020-10-21 09:50**MOT test number** 397173719690**Result** ✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #3 2019-10-22 12:47**MOT test number** 156051957391**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2018-10-17 12:25**MOT test number** 117842740675**Result** ✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt



| | |
|-----------------|---|
| MOT #1 | 2018-10-17 09:44 |
| MOT test number | 314472145900 |
| Result | ✗ Failed |
| Minor | Nearside Front Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i)) |
| Fail | Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt |
| Fail | Offside Front Windscreen washer not working (3.5 (a)) |
| Fail | Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
26 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 277 |
| MOT expiry date | 26 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | B |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,000 |
| Auction value | £ 15,000 |
| Average private trade value | £ 15,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2015-09-30 |
| Last registration | 2024-02-27 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-09-30 | 6 mi |
| Registration #2 | 2018-10-17 | 23.107 mi |
| Registration #3 | 2018-10-17 | 23.108 mi |
| Registration #4 | 2019-10-22 | 31.834 mi |
| Registration #5 | 2020-10-21 | 39.206 mi |
| Registration #6 | 2021-05-20 | 43.132 mi |
| Registration #7 | 2021-05-20 | 43.132 mi |
| Registration #8 | 2022-05-20 | 55.277 mi |
| Registration #9 | 2022-05-20 | 55.277 mi |
| Registration #10 | 2022-05-20 | 55.277 mi |
| Registration #11 | 2022-05-20 | 55.277 mi |
| Registration #12 | 2022-05-20 | 55.277 mi |
| Registration #13 | 2022-05-20 | 55.277 mi |
| Registration #14 | 2022-05-20 | 55.277 mi |
| Registration #15 | 2022-05-20 | 55.277 mi |
| Registration #16 | 2022-05-20 | 55.277 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 83% |
| Children | 74% |
| Pedestrian | 33% |
| Safety systems | 40% |
| Overall rating | 67% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1766 mm |
| Height | 1631 mm |
| Length | 4078 mm |
| Wheel base | 2540 mm |
| Kerb weight | 1240 kg |
| Max. allowed weight | 1800 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | JBHA0024022 |