



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 BLUEHDI DSIRE
Colour	Purple
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	80.7 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-08-31
Pictures	5
Listing price	View report

WELCOME TO THE WORLD'S LARGEST PART EXCHANGE WELCOME

HNDLER PROTECT
Get Covered Today
Your In Safe Hands

WELCOME TO THE WORLD'S LARGEST PART EXCHANGE
LOW RATE FINANCE
1 – 5 YEARS

WELCOME TO THE WORLD'S LARGEST PART EXCHANGE
97 POINT PRE-DELIVERY INSPECTION AS STANDARD

source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-06
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #9	2023-09-20 09:59
MOT test number	124852101248
Result	✓ Passed
Next expiry date	2024-10-06
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2023-09-19 09:52
MOT test number	885143463097
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2022-09-19 08:36
MOT test number	802759420559
Result	✓ Passed

**MOT #6** 2021-10-04 14:52**MOT test number** 622335197929**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2020-10-07 12:43**MOT test number** 835798369608**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #4** 2020-10-07 11:40**MOT test number** 973588876043**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #3** 2019-09-28 07:57**MOT test number** 861677161050**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2018-09-27 13:15**MOT test number** 167625573642**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #1	2017-10-25 10:41
MOT test number	265677447448
Result	✓ Passed
Advice	Front discs worn
Advice	Front pads low



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
6 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	6 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	SY64VW
Plate since	2019-09-29
Current registration	SY64VW
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-10-31
Last registration	2023-09-20
Complete history	See info



Registration #1	2014-10-31	23 mi
Registration #2	2017-10-25	60.549 mi
Registration #3	2018-09-27	76.737 mi
Registration #4	2019-09-28	81.230 mi
Registration #5	2020-10-07	84.794 mi
Registration #6	2020-10-07	84.794 mi
Registration #7	2020-10-07	84.794 mi
Registration #8	2020-10-07	84.794 mi
Registration #9	2020-10-07	84.794 mi
Registration #10	2020-10-07	84.794 mi
Registration #11	2020-10-07	84.794 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1598 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBGX3002976