



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | VAUXHALL |
| Model | AGILA SE |
| Colour | Brown |
| Year of manufacture | 2014 |
| Top speed | 106 mph |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 93 BHP |
| Max. torque | 118 Nm at 4.800 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 40.9 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 131 g/km |
| CO2 label | E |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-04-08 |
| Pictures | 20 |
| Listing price | View report |



source: [cargurus.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-28 |
| Pictures | 20 |
| Listing price | View report |



source: [heycar.co.uk](#)

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2025-04-01 |
| MOT pass rate | 89 % |
| MOT passed | 8 |
| Failed MOT tests | 1 |
| Total advice items | 4 |
| Total items failed | 2 |

| | |
|-------------------------|------------------|
| MOT #9 | 2024-03-08 14:51 |
| MOT test number | 145151795358 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-01 |

| | |
|---|------------------|
| MOT #8 | 2024-03-07 10:27 |
| MOT test number | 965110440709 |
| Result | ✗ Failed |
| Fail Offside Front Suspension rod ball joint dust cover no longer prevents the ingress of dirt drop link (5.3.4 (b) (ii)) | |
| Fail Nearside Front Suspension rod ball joint dust cover no longer prevents the ingress of dirt drop link (5.3.4 (b) (ii)) | |

| | |
|------------------------|------------------|
| MOT #7 | 2023-03-23 12:19 |
| MOT test number | 276342630302 |
| Result | ✓ Passed |

| | |
|--|------------------|
| MOT #6 | 2022-04-02 12:25 |
| MOT test number | 758705991182 |
| Result | ✓ Passed |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened discs lipped (1.1.14 (a) (ii)) | |

**MOT #5** 2021-06-09 08:36**MOT test number** 332491726087**Result** ✓ Passed**MOT #4** 2020-07-28 14:14**MOT test number** 560165968682**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2019-07-31 12:44**MOT test number** 783724790461**Result** ✓ Passed**MOT #2** 2018-08-06 11:02**MOT test number** 252552336977**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #1** 2017-07-24 14:15**MOT test number** 895030581548**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
1 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 1 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | YA14FVY |
| Plate since | 2019-06-29 |
| Current registration | YA14FVY |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 12 |
| First mileage registration | 2014-08-21 |
| Last registration | 2024-03-08 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-08-21 | 16 mi |
| Registration #2 | 2017-07-24 | 16.302 mi |
| Registration #3 | 2018-08-06 | 20.671 mi |
| Registration #4 | 2019-07-31 | 27.031 mi |
| Registration #5 | 2020-07-28 | 32.362 mi |
| Registration #6 | 2021-06-09 | 36.264 mi |
| Registration #7 | 2022-05-20 | 39.277 mi |
| Registration #8 | 2023-05-20 | 42.290 mi |
| Registration #9 | 2024-03-08 | 45.303 mi |
| Registration #10 | 2024-03-08 | 48.316 mi |
| Registration #11 | 2024-03-08 | 51.329 mi |
| Registration #12 | 2024-03-08 | 54.342 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1932 mm |
| Height | 1590 mm |
| Length | 3740 mm |
| Wheel base | 2360 mm |
| Kerb weight | 1065 kg |
| Max. allowed weight | 1485 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | K12B - 1849486LUY |