





report date: 2024-03-29

#### General information

Make	CITROEN
Model	C4 BLUEHDI FLAIR
Colour	Red
Year of manufacture	2016
Top speed	114 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

#### Entry 2

Date 2021-07-10

Pictures 20

Listing price <u>View report</u>









source: heycar.co.uk

#### Entry 1

Date 2021-06-07

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



**EO160FX** 

report date: 2024-03-29

# MOT history

MOT expiry date	2025-03-29
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	12
Total items failed	8

MOT #10	2024-03-14 15:33
MOT test number	487545194427
Result	✓ Passed
Next expiry date	2025-03-29
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #9	2024-03-14 12:19
MOT test number	964347522358
Result	<b>X</b> Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #8		2023-03-24 12:07
MOT test	number	259361239868
Result		✓ Passed
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

 MOT #7
 2022-03-30 12:17

 MOT test number
 927239495798

MOT #6 2022-03-21 16:06

**MOT test number** 427633438981

Result × Failed

**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice** Gearbox mounting defective

Fail Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #5 2021-06-24 10:23

**MOT test number** 545510432919

**Result** ✓ Passed

MOT #4 2021-01-11 16:18

**MOT test number** 761317490749

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2020-01-03 12:06 600270336434 **MOT test number** Result ✓ Passed MOT #2 2020-01-03 12:06 **MOT** test number 248371227707 Result × Failed Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a)) Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))

MOT test number

Result

Advice
Front Tyre slightly damaged/cracking or perishing both tyres lightly perished (5.2.3 (d) (ii))

Advice
Rear Tyre slightly damaged/cracking or perishing both tyres lightly perished (5.2.3 (d) (ii))

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	29 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



EO16OFX report date: 2024-03-29

Owner history

e mier meeory	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-03-14
Last registration	2024-03-14
Complete history	See info



Registration #1	2016-03-14	7 mi
Registration #2	2019-01-14	18.937 mi
Registration #3	2020-01-03	31.634 mi
Registration #4	2020-01-03	31.634 mi
Registration #5	2021-01-11	45.980 mi
Registration #6		11.777 es
Registration #7	2021-06-24	50.991 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		0.00 44
Registration #13		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

# Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1068 kg
Max. allowed weight	1610 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHA0116115

CarCheck.co.uk page 12/12