





report date: 2024-03-28

### General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Red
Year of manufacture	2011
Top speed	93 mph
0 - 60 mph	17.0 seconds
Gearbox	4 speed automatic

# Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 сс
Cylinders	3
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	54.3 mpg
CO2 emission	122 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history

### Entry 1

Date 2022-02-25


Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

Advice

MOT expiry date	2024-12-29
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	25
Total items failed	5

MOT #13	2023-12-30 13:27
MOT test number	534568630101
Result	✓ Passed
Next expiry date	2024-12-29

MOT #12	2023-12-30 13:27
MOT test number	386800836756
Result	<b>X</b> Failed
Pass with rectification	Front Position lamp with a multiple light source more than 1/2 not functioning
(4.2.1 (a) (ii))	

MOT #11	2022-11-18 16:37
MOT test number	357057338638
Result	✓ Passed

MOT #10	2021-09-06 10:40	
MOT test	number 200547313795	
Result	✓ Passed	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Rear wiper split	

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/13



bush (5.3.4 (a) (i))

**AU61USZ** 

report date: 2024-03-28

MOT #9 2020-08-27 14:56

**MOT test number** 489799123530

**Result** ✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

MOT #8 2019-08-30 15:25

**MOT test number** 350458342019

Result \rightarrow Passed

MOT #7 2018-08-31 15:17

**MOT test number** 157353595740

Result / Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

CarCheck.co.uk page 4/13



**Advice** 

**AU61USZ** 

report date: 2024-03-28

**MOT #6** 2018-08-31 10:13 **MOT** test number 160588359001 Result **X** Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i)) **Advice** Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) Fail Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i)) Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

MOT #5		2017-09-01 10:22
<b>MOT</b> test	number	776335634042
Result		✓ Passed
Advice	Offside Rear tyre outer side wall perished	
Advice	Offside Front Tyre worn close to the legal limit outer edge worn (4.1.E.1)	
Advice	Nearside Rear tyre outer side wall perished	
Advice	Nearside Front Tyre worn close to the legal limit on 3mm and outer edge balding	g (4.1.E.1)

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4	2016-09-06 14:56
MOT test number	329633429191
Result	<b>✓</b> Passed
Advice Nearside Front tyre worn on outer edge	

Advice Nearside Front t	yre worn on outer edge
MOT #3	2015-09-04 11:29
MOT test number	159348222723
Result	✓ Passed
MOT #2	2014-09-05 10:56
MOT test number	768678944238
Result	✓ Passed
MOT #1	2014-09-05 10:56
MOT test number	215598444239
Result	× Failed
Pass with rectification Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)	

CarCheck.co.uk page 6/13



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	29 December 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	NIP. IUK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-06
Last registration	2023-12-30
Complete history	See info



Registration #1	2011-09-06	7 mi
Registration #2	2014-09-05	5.780 mi
Registration #3	2015-09-04	8.133 mi
Registration #4	2016-09-06	11.949 mi
Registration #5	2017-09-01	15.250 mi
Registration #6	2018-08-31	18.758 mi
Registration #7	2018-08-31	18.758 mi
Registration #8		11.117 au
Registration #8 Registration #9		11.77 m
-		11.777 ea 11.777 ea
Registration #9		11.777 es 11.777 es 11.777 es
Registration #9 Registration #10		11.777 es 11.777 es 11.777 es
Registration #9 Registration #10 Registration #11		11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



AU61USZ report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

## Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	144639

CarCheck.co.uk page 13/13