



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS TDI SE
Colour	Silver
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	156 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-05-28
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-04-11
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	76
Total items failed	14

MOT #19 2024-04-12 13:33

MOT test number 236389469552

Result ✓ Passed

Next expiry date 2025-04-11

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #18 2023-02-09 13:48

MOT test number 520137585879

Result ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both O/S/R and N/S/R (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both N/S/F and O/S/F (1.1.14 (a) (ii))

**MOT #17**

2023-02-09 10:11

**MOT test number**

857991998124

**Result**

✗ Failed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both N/S/F and O/S/F (1.1.14 (a) (ii))
- Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both O/S/R and N/S/R (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Shock absorbers missing (5.3.2 (a) (ii))

**MOT #16**

2021-09-16 15:23

**MOT test number**

620686638692

**Result**

✓ Passed

- Advice** Os sill damaged
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #15**

2020-11-17 16:22

**MOT test number**

756878393592

**Result**

✓ Passed

- Advice** Engine / bay covers , under guards & mouldings fitted , restricting views
- Advice** Note ; Noise from Offside front wheel on rotation , suspect bearing
- Advice** Exhaust ; Centre sleeve joint deteriorated
- Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated splitting (5.3.4 (b) (i))

**MOT #14**

2020-11-17 13:56

**MOT test number**

692998902451

**Result****✗ Failed****Advice** Exhaust ; Centre sleeve joint deteriorated**Fail** Nearside Rear Tyre has ply or cords exposed at inner edge (5.2.3 (d) (ii))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated splitting (5.3.4 (b) (i))**Advice** Engine / bay covers , under guards & mouldings fitted , restricting views**Advice** Note ; Noise from Offside front wheel on rotation , suspect bearing**Fail** Offside Rear Tyre has ply or cords exposed at inner edge (5.2.3 (d) (ii))**MOT #13**

2019-11-14 15:26

**MOT test number**

454928905912

**Result****✓ Passed****Advice** Driveshafts ; Nearside outer c.v. joint slightly noisy**Advice** Nearside Front Tyre worn close to legal limit/worn on edge main tread areas at 1.6 mm (5.2.3 (e))**Advice** Note ; wheel fixings covered , engine / bay covers , under guards & mouldings fitted , restricting views**Advice** Offside Front Tyre worn close to legal limit/worn on edge areas of main tread at 2.0 mm , secondary tread bald on edges (5.2.3 (e))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated minor split (5.3.4 (b) (i))

**MOT #12**

2019-11-14 15:26

**MOT test number**

672256852793

**Result**

✗ Failed

**Pass with rectification**

Nearside Headlamp aim projected beam image is obviously incorrect bulb insecure (4.1.2 (c))

**Minor**

Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated minor split (5.3.4 (b) (i))

**Advice**

Note ; wheel fixings covered , engine / bay covers , under guards & mouldings fitted , restricting views

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge areas of main tread at 2.0 mm , secondary tread bald on edges (5.2.3 (e))

**Pass with rectification**

Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt clip missing (6.1.7 (g) (ii))

**Advice**

Driveshafts ; Nearside outer c.v. joint slightly noisy

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge main tread areas at 1.6 mm (5.2.3 (e))

**MOT #11**

2018-11-05 16:28

**MOT test number**

478740829676

**Result**

✓ Passed

**Advice**

Note ; Engine / bay covers , under guards & mouldings fitted , restricting views

**Advice**

Tyres ; Tread balding on outer edge , Offside front

**Advice**

Suspension ; Anti-roll bar link upper ball joint seal has minor split

**Advice**

Note ; Drivers door sticky to open from inside

**MOT #10**

2018-11-01 15:09

**MOT test number**

226510931386

**Result****✗ Failed****Advice** Note ; Drivers door sticky to open from inside**Advice** Brakes ; \*\*\* Pads worn thin , Offside rear at limit**Pass with rectification** Nearside Headlamp light intensity severely reduced dip bulb insecure (4.1.4 (a))**Fail** Nearside Front Brake hose connection leaking on a hydraulic braking system at caliper (1.1.12 (c) (ii))**Advice** Note ; Offside rear wheel has restricted rotation , suspect brake related**Fail** Offside Rear Coil spring fractured or broken at upper end (5.3.1 (b) (i))**Advice** Tyres ; Tread balding on outer edge , Offside front**Advice** Note ; Brake imbalance , see printout**Advice** Note ; Engine / bay covers , under guards & mouldings fitted , restricting views**Advice** Brakes ; Brake discs corroded , may be weakened , both rear**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Suspension ; Anti-roll bar link upper ball joint seal has minor split**MOT #9**

2017-06-07 07:34

**MOT test number**

212037430734

**Result****✓ Passed****Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



<b>MOT #8</b>	2016-07-04 12:43
<b>MOT test number</b>	617349182412
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
<b>Advice</b>	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

<b>MOT #7</b>	2015-07-08 16:50
<b>MOT test number</b>	155129285170
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

<b>MOT #6</b>	2014-03-14 16:06
<b>MOT test number</b>	829103174029
<b>Result</b>	✓ Passed
<b>Notice</b>	O/s/r tyre bald on inner edge and cuts in.
<b>Advice</b>	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
<b>Notice</b>	N/s/r tyre tread bald on inner edge and cuts in plus 2 nails in tread.
<b>Advice</b>	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



**MOT #5** 2014-03-14 16:06**MOT test number** 437203574027**Result** ✗ Failed**Notice** O/s/r tyre bald on inner edge and cuts in.**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Notice** N/s/r tyre tread bald on inner edge and cuts in plus 2 nails in tread.**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2013-03-12 16:36**MOT test number** 485141473012**Result** ✓ Passed**Notice** The rear brake pads are wearing thin.**Notice** The drivers seatbelt is twisted.**Notice** The front passenger seatbelt is twisted.**Notice** Under-trays fitted obscuring some underside components**Notice** The drivers seatbelt is slow to retract.**MOT #3** 2012-03-19 09:35**MOT test number** 135919772406**Result** ✓ Passed**Notice** Rear tyres slightly mishaped on inner edges.**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-03-28 20:09
MOT test number	158167181017
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-03-28 20:09
MOT test number	855557481051
Result	✗ Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
11 April 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	11 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-05-12
Last registration	2024-04-12
Complete history	<a href="#">See info</a>



Registration #1	2008-05-12	19 mi
Registration #2	2011-03-28	18.763 mi
Registration #3	2012-03-19	27.319 mi
Registration #4	2013-03-12	46.081 mi
Registration #5	2014-03-14	61.575 mi
Registration #6	2015-07-08	76.184 mi
Registration #7	2016-07-04	86.290 mi
Registration #8	2017-06-07	94.386 mi
Registration #9	2018-11-01	108.841 mi
Registration #10	2018-11-05	108.850 mi
Registration #11	2019-05-20	121.277 mi
Registration #12	2019-05-20	121.277 mi
Registration #13	2019-05-20	121.277 mi
Registration #14	2019-05-20	121.277 mi
Registration #15	2019-05-20	121.277 mi
Registration #16	2019-05-20	121.277 mi
Registration #17	2019-05-20	121.277 mi
Registration #18	2019-05-20	121.277 mi
Registration #19	2019-05-20	121.277 mi

More info >





Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1715 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKP 293807