





General information

Make	RENAULT
Model	TRAFIC SL27 DCI S/R P/V
Colour	Black
Year of manufacture	2011
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP	0 < 101 A
Max. torque	290 Nm at 1.600 rpm	101 - 120 B
Engine capacity	1.996 cc	121 - 140 E
Cylinders	4	141 - 165 F G
Fuel type	Diesel	166 - 185
Consumption city	33.2 mpg	186 - 225 J
Consumption extra urban	41.5 mpg	225+ L
Consumption combined	38.1 mpg	





Internet history

Entry 1

Date Pictures

16

- -

Listing price

View report

2021-09-01









source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-13
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	32
Total items failed	7

MOT #14	2023-07-14 15:15
MOT test number	474543642786
Result	✓ Passed
Next expiry date	2024-07-13
Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting (5.3.4 (a) (i))	in excessive movement
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting (5.3.4 (a) (i))	g in excessive movement
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	14 (a) (ii))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #13	2022-07-06 15:44
MOT test number	354433149594
Result	✓ Passed

MOT #12		2021-02-20 10:08
MOT test	number	344344405438
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #11		2020-02-25 10:23
MOT test	number	360175582353
Result		✓ Passed
Advice (a) (i))	Offside Front Macpherson strut pin or bush worn but not resulting ir	n excessive movement (5.3.4
Advice	Nearside Rear tyre slightly stepped	

MOT #10		2019-02-13 15:17
MOT test	number	296638545840
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2018-02-14 12:29
MOT test number	531775687748
Result	✓ Passed
AdviceFuel high pressure pumpAdviceOffside Rear Tyre worn closed	as a misting of fuel se to the legal limit 3mm (4.1.E.1)
Auvice Offside Real Tyre worth cit	

MOT #8	2018-02-07 15:33
MOT test number	416684352371
Result	🗙 Failed
Fail Nearside Front Front constant velocity joint is insecure (2.5.C.1b)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm 195/65/16 c (4.1.E.	1)
Fail Nearside Front Outer Suspension arm has excessive play in a ball joint bottom bal	l joint (2.4.G.2)
Advice Fuel high pressure pump has a misting of fuel	
Advice Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)	





MOT #7	2017-01-20 15:08	
MOT test number	969654399387	
Result	✓ Passed	
Advice Offside Front Macpherson strut has slight movement at the upper attachr	nent (2.5.A.1c)	
MOT #6	2017-01-20 11:12	
MOT test number	625278992905	
Result	🗙 Failed	
Fail Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)		
Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)		
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)		
MOT #5	2016-01-22 13:00	

MOT test	number	680078356632
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	



MW600AA report date: 2024-03-29

MOT #4	2016-01-22 10:06
MOT test number	890694864820
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #3	2015-01-27 13:15
MOT test number	909097125062
Result	Passed
Advice Offside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)	


MOT #2	2015-01-22 15:02
MOT test number	266382725047
Result	🗙 Failed
Advice Offside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)	
Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #1		2014-01-22 14:40
MOT test	number	556002724078
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



MW600AA report date: 2024-03-29

Tax & MOT check







Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Lawe
AMPL
AMP

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-02-16
Last registration	2023-07-14
Complete history	See info



Registration #1	2011-02-16	15 mi
Registration #2	2014-01-22	26.847 mi
Registration #3	2015-01-22	33.476 mi
Registration #4	2015-01-27	33.476 mi
Registration #5	2016-01-22	40.536 mi
Registration #6	2016-01-22	40.536 mi
Registration #7	2017-01-20	47.889 mi
Registration #8	2017-01-20	47.890 mi
Registration #9		11.777 mi
Registration #9 Registration #10		00.000 est
		01.000 est 01.000 est 01.000 est
Registration #10		00.000 est 0.000 est 00.000 est 00.000 est
Registration #10 Registration #11		00.000 460 00.000 460 00.000 460 00.000 460 00.000 460
Registration #10 Registration #11 Registration #12		00.000 460 0.000 460 00.000 460 00.000 460 00.000 460 00.000 460
Registration #10Registration #11Registration #12Registration #13		00.000 460 0.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1904 mm
Height	1955 mm
Length	4782 mm
Kerb weight	1660 kg
Max. allowed weight	2770 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C175241