





report date: 2024-03-29

General information

Make	FORD
Model	FUSION FUSION +
Colour	Blue
Year of manufacture	-
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history


Entry 1

Date 2021-07-29

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT #16 2022-09-16 16:28

MOT test number 812188841029

Result ✓ Passed

Next expiry date 2023-09-15

Advice Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #15 2022-09-16 13:22

MOT test number 799011156454

Result X Failed

Advice Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

DANGEROUS Nearside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

DANGEROUS Offside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MOT #14 2021-08-06 13:32

MOT test number 785892673003

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13 2020-08-26 08:32

MOT test number 209646316272

Result
✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12

MOT test number

Result

Advice Exhaust emits black smoke during acceleration (8.2.1.2 (g))

MOT test number

195935645614

Result

Advice Nearside Rear Nail in tyre x2

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

S19944312611

Result

Advice 2 nails nearside rear tyre

Advice Rear exhaust box corroded.

Advice Centre seat belt minor damage

Advice Both front tyres worn on edges

 MOT #9
 2016-09-15 08:15

 MOT test number
 439070261101

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

✓ Passed

MOT #8 2016-09-14 13:49
MOT test number 710724661763

Result X Failed

Fail Rear fog lamp not working (1.3.2b)

Fail Offside Windscreen washer provides insufficient washer liquid jet blocked (8.2.3)

Fail Power steering component(s) leaking power steering rack leaking oil (2.3.3b)

MOT #7 2015-09-21 12:52

MOT test number 728915047162

Result
✓ Passed

MOT #6 2014-08-27 10:15

MOT test number 115649134202

Result

Advice Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2014-08-20 12:19

MOT test number 219572534251

Result X Failed

Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Power steering component(s) leaking (2.3.3b)

Notice Steering judders and slight roghness


Fail Offside Headlamp aim too high and too far to the right. (1.8)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



report date: 2024-03-29




MOT #3		2012-09-05 09:13
MOT test	number	466129142212
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Oil leak to steering rack unable to fully inspect due to covers	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Offside front tyre worn on inner edge	
Notice	Oil leak	
Notice	Under-trays fitted obscuring some underside components	
Notice	Plastic cill covers fitted	

CarCheck.co.uk page 6/13



report date: 2024-03-29



MOT #1	2011-02-21 08:38
MOT test number	365872851050
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners defect it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	UK NIE.
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-01
Last registration	2022-09-16
Complete history	See info



Registration #1	2008-03-01	28 mi
Registration #2	2011-02-21	21.310 mi
Registration #3	2012-09-05	32.335 mi
Registration #4	2013-08-23	40.150 mi
Registration #5	2014-08-20	48.105 mi
Registration #6	2014-08-27	48.226 mi
Registration #7	2015-09-21	56.629 mi
Registration #8	2016-09-14	63.703 mi
Registration #9	2016-09-15	63.703 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.117 es
Registration #13		11.117 es
Registration #14		
		n.m.
Registration #15		11.77 m
_		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1237 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	43
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/3

Number of axles 2

Engine number 8B83929