



report date: 2024-03-29

General information

Make	KIA
Model	CEED CRDI VR-7
Colour	Black
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	235 Nm at 2.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	70.6 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C



**MOT history**

MOT expiry date	2021-01-30
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	30
Total items failed	18

MOT #13 2020-01-31 14:52**MOT test number** 951325568514**Result** Passed**Next expiry date** 2021-01-30**Minor** Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2020-01-30 09:59**MOT test number** 939246368392**Result** Failed**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #11** 2019-01-24 14:47**MOT test number** 452467723411**Result** Passed



MOT #10	2019-01-24 13:48
MOT test number	111812859475
Result	✗ Failed
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #9	2018-06-14 12:49
MOT test number	820748239421
Result	✓ Passed
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
Advice	Knock on steering, no visible worn components
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
Advice	Items removed from driver's view prior to test
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #8** 2018-06-11 09:29**MOT test number** 248967988755**Result** ✗ Failed

- Advice** Knock on steering, no visible worn components
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Fail** Offside Rear Reversing lamp switch does not operate automatically when reverse gear is selected (4.6.3 (a))
- Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Rear Reversing lamp switch does not operate automatically when reverse gear is selected (4.6.3 (a))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

MOT #7 2017-06-06 11:50**MOT test number** 518020594950**Result** ✓ Passed

- Advice** Offside Front strong advise tyre badly worn on inner edge and rest of tread low
- Advice** Grease around nearside inner driveshaft gaiter no splits and gaiter is secure
- Advice** Nearside Front strong advise tyre worn on outer edge and rest of tread close to legal limit
- Advice** Both rear tyre outer sidewalls perished slightly

**MOT #6** 2016-06-01 09:51**MOT test number** 836394534830**Result** ✓ Passed**Advice** Nearside Front tyre worn slightly on outer edge of tread**Advice** Nearside Front inner driveshaft has grease around it but is secure and not split**MOT #5** 2016-05-31 15:17**MOT test number** 740836212209**Result** ✗ Failed**Advice** Nearside Front tyre worn slightly on outer edge of tread**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front inner driveshaft has grease around it but is secure and not split**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Front suspension ball joint dust cover damaged, but preventing the ingress of dirt lower joint (2.4.G.2)**MOT #4** 2015-05-12 11:06**MOT test number** 279442535115**Result** ✓ Passed**Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #3** 2015-05-12 11:06**MOT test number** 935652135133**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)



MOT #2	2014-02-28 14:31
MOT test number	786989154014
Result	✓ Passed

MOT #1	2014-02-28 11:02
MOT test number	448399654080
Result	✗ Failed
<div><div>Fail</div>Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div> <div><div>Fail</div>Offside Registration plate lamp not working (1.1.C.1d)</div> <div><div>Fail</div>Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div> <div><div>Fail</div>Nearside Front position lamp(s) not working (1.1.A.3b)</div> <div><div>Fail</div>Nearside Direction indicator not working (1.4.A.2c)</div>	



Tax & MOT check

X

Untaxed

Tax expired:
17 February 2021

X

MOT

Expired:
30 January 2021

Tax status	Expired at 17 February 2021
Days left	1167 days too late
MOT expiry date	30 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-03-04
Last registration	2020-01-31
Complete history	See info



Registration #1	2011-03-04	26 mi
Registration #2	2014-02-28	44.660 mi
Registration #3	2014-02-28	44.660 mi
Registration #4	2015-05-12	52.884 mi
Registration #5	2016-05-31	63.002 mi
Registration #6	2016-06-01	63.002 mi
Registration #7	2017-06-06	73.410 mi
Registration #8	2018-06-06	83.818 mi
Registration #9	2019-06-06	94.226 mi
Registration #10	2020-01-31	104.634 mi
Registration #11	2020-01-31	104.634 mi
Registration #12	2020-01-31	104.634 mi
Registration #13	2020-01-31	104.634 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1480 mm
Length	4260 mm
Wheel base	2650 mm
Kerb weight	1468 kg
Max. allowed weight	1820 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	D4FBBZ297252
---------------	--------------