



report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO 725 X L2 HDI
Colour	White
Year of manufacture	2013
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	50.4 mpg
CO2 emission	147 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-03
Pictures	30
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-20
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	32
Total items failed	0

MOT #12	2023-06-21 06:52
MOT test number	476684540132
Result	✓ Passed
Next expiry date	2024-06-20
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge very close to limit (5.2.3 (e))

**MOT #11**

2023-06-20 15:35

**MOT test number**

804221770830

**Result**

✗ Failed

**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge very close to limit (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2022-05-31 13:38

**MOT test number**

675449360288

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2022-05-26 11:18**MOT test number** 401585327137**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Headlamp aim too low (4.1.2 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**MOT #8** 2021-06-04 10:38**MOT test number** 352725075011**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2020-02-06 14:05**MOT test number** 216034841834**Result** ✓ Passed



<b>MOT #6</b>	2020-02-05 10:49
<b>MOT test number</b>	379406865901
<b>Result</b>	✗ Failed
<b>MAJOR</b> Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))	

<b>MOT #5</b>	2019-03-01 14:57
<b>MOT test number</b>	623041131966
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2019-03-01 10:32
<b>MOT test number</b>	244810231887
<b>Result</b>	✗ Failed
<b>MAJOR</b> Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
<b>MAJOR</b> Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
<b>MAJOR</b> Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
<b>Minor</b> Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

<b>MOT #3</b>	2018-02-21 11:34
<b>MOT test number</b>	293064726467
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2017-03-02 16:34
<b>MOT test number</b>	195406561865
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2016-02-17 11:10
<b>MOT test number</b>	561571805019
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
20 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	20 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-01
Last registration	2023-06-21
Complete history	<a href="#">See info</a>



Registration #1	2013-03-01	8 mi
Registration #2	2016-02-17	41.461 mi
Registration #3	2017-03-02	60.470 mi
Registration #4	2018-02-21	81.806 mi
Registration #5	2019-03-01	100.880 mi
Registration #6	2019-03-01	100.883 mi
Registration #7	2020-02-05	115.940 mi
Registration #8	2020-03-20	121.277 mi
Registration #9	2020-03-20	121.277 mi
Registration #10	2020-03-20	121.277 mi
Registration #11	2020-03-20	121.277 mi
Registration #12	2020-03-20	121.277 mi
Registration #13	2020-03-20	121.277 mi
Registration #14	2023-06-21	121.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	6
Number of seats	5
Engine number	JBEM0190798