

Ford



## General information

| Make                | FORD           |
|---------------------|----------------|
| Model               | B-MAX ZETEC    |
| Colour              | Black          |
| Year of manufacture | 2015           |
| Top speed           | 106 mph        |
| Gearbox             | 5 speed Manual |

# Engine & fuel consumption

| Power                   | 66 kW / 90 HP / 89 BHP |
|-------------------------|------------------------|
| Max. torque             | 128 Nm at 4.000 rpm    |
| Engine capacity         | 1.388 cc               |
| Cylinders               | 4                      |
| Fuel type               | Petrol                 |
| Consumption city        | 35.8 mpg               |
| Consumption extra urban | 57.7 mpg               |
| Consumption combined    | 47.1 mpg               |
| CO2 emission            | 139 g/km               |
| CO2 label               | E                      |





| Internet history |             |
|------------------|-------------|
| Entry 1          |             |
| Date             | 2021-01-29  |
| Pictures         | 1           |
| Listing price    | View report |



source: autoonline.co.uk



## MOT history

| MOT expiry date    | 2024-11-02 |
|--------------------|------------|
| MOT pass rate      | 75 %       |
| MOT passed         | 6          |
| Failed MOT tests   | 2          |
| Total advice items | 4          |
| Total items failed | 3          |

| MOT #8           | 2023-11-03 14:54 |
|------------------|------------------|
| MOT test number  | 840037069351     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-11-02       |

| MOT #7          | 2023-01-02 15:36 |
|-----------------|------------------|
| MOT test number | 589099928429     |
| Result          | ✓ Passed         |

| MOT #6                  |  | 2023-01-02 15:36 |
|-------------------------|--|------------------|
| MOT test number         |  | 142609069731     |
| Result                  |  | 🗙 Failed         |
| Pass with rectification | Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) |                  |

| MOT #5          | 2022-01-17 12:25 |
|-----------------|------------------|
| MOT test number | 928368463379     |
| Result          | ✓ Passed         |





| МОТ #4  | 2022-01-15 16:34       |
|---|------------------------|
| MOT test number   | 282223524523           |
| Result  | 🗙 Failed               |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge bald on | inner edge (5.2.3 (e)) |
| FailOffside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))          |                        |
| Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))                   |                        |
|   |                        |
| MOT #3  | 2021-01-15 14:37       |
| MOT test number   | 704378672154           |
| Result  | ✓ Passed               |
| NOT #2  | 2010 12 02 12 21       |
| MOT #2  | 2019-12-03 13:31       |
| MOT test number   | 122436363897           |
| Result  | ✓ Passed               |
|   |                        |
| MOT #1  | 2018-12-03 10:12       |
| MOT test number   | 686216460937           |

| MOT test | number  | 686216460937 |
|----------|---|--------------|
| Result   |   | ✓ Passed     |
| Advice   | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                                 |              |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))  |              |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) |              |



Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 November 2024 | ✓<br>MOT<br>Expires:<br>2 November 2024 |
|---|---|
| Tax status                                | Valid until 1 November                  |
| Days left                                 | 185                                     |
| MOT expiry date                           | 2 November 2024                         |
| Full MOT history                          | See MOT history                         |
| Tax calculation                           |   |

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | E          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |





### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |             |
|----------|-------------|
| Date     | FER I       |
| Category | <br>A PLANE |
| Туре     |             |
| Damage 2 | AMPLE       |
| Damage 2 | E Stand     |
| Date     | *           |
| Category | <br>ante.   |
| Туре     |             |

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec |             |
|--|-------------|
| ************   |             |
| ********   |             |
| ******   |             |
| ************   |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this FORD had different number plates.  |             |
| Number of plates   | ,           |
| Carrent registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  |             |





### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 10         |
| First mileage registration | 2015-12-07 |
| Last registration          | 2023-11-03 |
| Complete history           | See info   |



| Registration #1  | 2015-12-07 | 17 mi      |
|------------------|------------|------------|
| Registration #2  | 2018-12-03 | 27.565 mi  |
| Registration #3  | 2019-12-03 | 34.013 mi  |
| Registration #4  | 2021-01-15 | 40.346 mi  |
| Registration #5  |            | 11.777 mi  |
| Registration #6  |            | 11.777 est |
| Registration #7  |            | 11.777 mi  |
| Registration #8  |            | 11.777 esi |
| Registration #9  |            | 11.777 mi  |
| Registration #10 |            | 10.300 est |

More info >





### Car features

| S0225  | Air conditioning |
|--------|------------------|
| \$0295 |                  |
| S0482  |                  |
| \$0501 |                  |
| S0566  |                  |
| S0567  |                  |
| S0569  |                  |

# Safety ratings

Number of seats

Number of axles

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 92%             |
| Children       | 84%             |
| Pedestrian     | 67%             |
| Safety systems | 71%             |
| Overall rating | 83%             |
| Video          | see crash video |



| Dimensions & weight    |                       |
|------------------------|-----------------------|
| Width                  | 2067 mm               |
| Height                 | 1604 mm               |
| Length                 | 4077 mm               |
| Wheel base             | 2489 mm               |
| Kerb weight            | 1760 kg               |
| Max. allowed weight    | 1745 kg               |
| Additional information |                       |
| Fuel delivery          | Multi-Point Injection |
| Number of doors        | 5                     |

5

2