



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT S TDI
Colour	Silver
Year of manufacture	2010
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	C





Internet history

Entry 3

Date 2022-01-14

Pictures 13

Listing price [View report](#)




source: cargurus.co.uk

Entry 2

Date 2021-10-07

Pictures 13

Listing price [View report](#)



source: cargurus.co.uk

Entry 1

Date 2021-10-05

Pictures 13

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-29
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	21
Total items failed	3

MOT #15 2023-10-19 09:32

MOT test number 923511898323

Result ✓ Passed

Next expiry date 2024-10-29

Minor Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated Both sides (5.3.4 (b) (i))

Minor Offside Rear Direction indicator with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))

Minor Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush, both sides (5.3.4 (a) (i))

MOT #14 2022-10-01 12:30

MOT test number 698572930865

Result ✓ Passed

Minor Offside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))

MOT #13 2021-10-30 09:17

MOT test number 992636991729

Result ✓ Passed

**MOT #12**

2021-03-23 09:22

MOT test number

644328935619

Result

✓ Passed

- Minor** Offside Rear Direction indicator with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11

2021-03-15 16:54

MOT test number

119133963394

Result

✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Rear Direction indicator with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Electronic parking brake warning indicates a malfunction (1.1.6 (e))

MOT #10

2020-03-13 16:33

MOT test number

996217838227

Result

✓ Passed

- Advice** Nearside Rear Tyre has nail in tread and perishing on tread
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Rear Tyre is perishing on tread

**MOT #9** 2020-03-13 08:55**MOT test number** 810010446471**Result** ✗ Failed**Advice** Nearside Rear Tyre has nail in tread and perishing on tread**DANGEROUS** Nearside Front Tyre has ply or cords exposed Worn bald inner tread (5.2.3 (d) (ii))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Offside Rear Tyre is perishing on tread**MOT #8** 2019-03-18 10:55**MOT test number** 363526057681**Result** ✓ Passed**MOT #7** 2017-06-08 11:14**MOT test number** 429660716021**Result** ✓ Passed**MOT #6** 2016-06-17 10:22**MOT test number** 381726917059**Result** ✓ Passed**MOT #5** 2016-06-17 10:22**MOT test number** 656393529312**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2015-07-25 12:45**MOT test number** 516076005297**Result** ✓ Passed



MOT #3	2015-07-25 11:21
MOT test number	307676705496
Result	✗ Failed
Fail	Nearside Body has a sharp edge caused by damage (6.1.C.1)
Fail	Nearside Outer Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #2	2014-06-28 11:06
MOT test number	239729074470
Result	✓ Passed

MOT #1	2013-06-14 14:48
MOT test number	765425263174
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
29 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	29 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 FV10WFZ
Plate since	2019-06-29
Current registration	 FV10WFZ
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-25
Last registration	2023-10-19
Complete history	See info



Registration #1	2010-06-25	20 mi
Registration #2	2013-06-14	34.992 mi
Registration #3	2014-06-28	41.942 mi
Registration #4	2015-07-25	48.877 mi
Registration #5	2015-07-25	48.880 mi
Registration #6	2016-06-17	53.536 mi
Registration #7	2016-06-17	53.536 mi
Registration #8	2017-06-08	58.006 mi
Registration #9	2019-03-18	69.115 mi
Registration #10	2020-03-13	75.179 mi
Registration #11	2020-03-13	75.179 mi
Registration #12	2020-03-13	75.179 mi
Registration #13	2020-03-13	75.179 mi
Registration #14	2020-03-13	75.179 mi
Registration #15	2020-03-13	75.179 mi
Registration #16	2020-03-13	75.179 mi
Registration #17	2020-03-13	75.179 mi
Registration #18	2020-03-13	75.179 mi
Registration #19	2020-03-13	75.179 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1266 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

CAY520261