



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Grey
Year of manufacture	2006
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-12-30
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	40
Total items failed	0

MOT #16 2023-12-18 16:38

MOT test number 866774491606

Result ✓ Passed

Next expiry date 2024-12-30

- Advice** Offside Rear outer sill is damaged but still okay
- Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15 2022-12-12 12:37

MOT test number 318331064533

Result ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** O/s/r outer sill damaged

**MOT #14** 2021-12-16 15:21**MOT test number** 185279566744**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**Advice** O/s/r outer sill damaged**MOT #13** 2021-12-16 09:55**MOT test number** 707162945243**Result** ✗ Failed**MAJOR** Offside Rear Suspension arm corroded and seriously weakened (5.3.3 (b) (i))**Advice** O/s/r outer sill damaged**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Play in steering rack inner joint(s)**MOT #12** 2020-12-08 12:27**MOT test number** 430433152717**Result** ✓ Passed**MOT #11** 2019-06-18 07:48**MOT test number** 590677166298**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Centre/rear & rear exhaust heatshields deteriorating**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Engine cover & undershield obscuring components**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2018-06-04 15:11

MOT test number

350441055221

Result

✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

2017-06-27 13:37

MOT test number

634071755152

Result

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Engine cover & undershield obscuring components
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8

2016-06-08 15:41

MOT test number

771359433181

Result

✓ Passed

MOT #7

2015-06-24 14:46

MOT test number

469945175105

Result

✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components



MOT #6	2014-06-25 11:37
MOT test number	517406374131
Result	✓ Passed
Notice	Emmissions too clean for macine to detect

MOT #5	2013-06-19 14:29
MOT test number	955690773115
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Faint roughness from nearside front wheel bearing
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)
Notice	Front wipers smear
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Notice	Slight knock through steering wheel

MOT #4	2012-06-18 16:01
MOT test number	705820972183
Result	✓ Passed

MOT #3	2011-06-20 09:58
MOT test number	166791171120
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)



MOT #2	2010-06-21 11:03
MOT test number	973452770170
Result	✓ Passed

MOT #1	2009-06-18 09:53
MOT test number	211359769119
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
30 December 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	30 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-06-30
Last registration	2023-12-18
Complete history	See info



Registration #1	2006-06-30	16 mi
Registration #2	2009-06-18	22.313 mi
Registration #3	2010-06-21	30.106 mi
Registration #4	2011-06-20	38.609 mi
Registration #5	2012-06-18	46.028 mi
Registration #6	2013-06-19	52.086 mi
Registration #7	2014-06-25	57.957 mi
Registration #8	2015-06-24	62.068 mi
Registration #9	2016-06-08	66.604 mi
Registration #10	2016-06-08	66.604 mi
Registration #11	2016-06-08	66.604 mi
Registration #12	2016-06-08	66.604 mi
Registration #13	2016-06-08	66.604 mi
Registration #14	2016-06-08	66.604 mi
Registration #15	2016-06-08	66.604 mi
Registration #16	2016-06-08	66.604 mi
Registration #17	2016-06-08	66.604 mi
Registration #18	2016-06-08	66.604 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1897 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	6R35775