



General information

Make	FORD
Model	FUSION STYLE PLUS
Colour	Black
Year of manufacture	2009
Top speed	103 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	95 BHP
Max. torque	128 Nm at 4.200 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 5

Date	2022-04-07
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 4

Date	2022-02-01
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 3

Date	2022-01-12
Pictures	8
Listing price	View report



source: [autoonline.co.uk](#)

Entry 2

Date	2021-12-29
------	------------

Pictures

6

Listing price

[View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date

2021-12-21

Pictures

1

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-06-27
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	46
Total items failed	15

MOT #21 2023-06-28 15:11**MOT test number** 757343809569**Result** Passed**Next expiry date** 2024-06-27

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material above side of fuel tank (1.1.11 (c))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #20 2023-06-16 11:57**MOT test number** 868928362622**Result** Failed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material above side of fuel tank (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #19** 2022-05-23 10:43**MOT test number** 207877607859**Result** ✓ Passed**MOT #18** 2021-09-23 15:25**MOT test number** 495410288519**Result** ✓ Passed**Advice** Brake pipes at rear of vehicle corroded especially in clips**Advice** Steering rack has am misting of oil**MOT #17** 2021-09-20 09:03**MOT test number** 716842300809**Result** ✗ Failed**Advice** Engine has a coolant leak**Fail** Offside Rear Direction indicator incorrect colour white light (4.4.3 (a))**Advice** Brake pipes at rear of vehicle corroded especially in clips**Fail** Nearside Rear Direction indicator incorrect colour white light (4.4.3 (a))**Advice** Offside Front Lower ball joint gaitor deteriorated slightly**Advice** Steering rack has am misting of oil**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #16** 2020-09-10 08:47**MOT test number** 138133308899**Result** ✓ Passed**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))



MOT #15	2020-09-10 08:47
MOT test number	289007863924
Result	✗ Failed
Pass with rectification	Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14	2019-09-14 09:47
MOT test number	457772244679
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Tyre slightly damaged/cracking or perishing all tyres[old] (5.2.3 (d) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #13**

2019-09-14 09:47

MOT test number

235375128987

Result

✗ Failed

Pass with rectification Central Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Pass with rectification Nearside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Tyre slightly damaged/cracking or perishing all tyres[old] (5.2.3 (d) (ii))

MOT #12

2018-09-17 08:37

MOT test number

503504620892

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11

2017-09-22 12:35

MOT test number

285741407460

Result

✓ Passed

MOT #10

2017-09-21 10:01

MOT test number

341583066046

Result

✗ Failed

Fail Offside Rear fog lamp not working (1.3.2b)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #9** 2016-08-30 10:25**MOT test number** 706367780367**Result** ✓ Passed**Advice** Screw in osr tyre**MOT #8** 2016-08-30 08:33**MOT test number** 451088954329**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Screw in osr tyre**MOT #7** 2015-09-17 09:39**MOT test number** 546930433643**Result** ✓ Passed**Advice** Centre Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Front brake discs some wear & corrosion**Advice** Items removed from drivers view prior to test**Advice** Internal headlamp adjuster altered to recheck lights

**MOT #6** 2015-09-17 09:39**MOT test number** 603347721050**Result** ✗ Failed**Advice** Internal headlamp adjuster altered to recheck lights**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front brake discs some wear & corrosion**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Items removed from drivers view prior to test**Advice** Centre Front registration plate delaminated but not likely to be misread (6.3.1d)**MOT #5** 2014-09-13 11:33**MOT test number** 699536354286**Result** ✓ Passed**MOT #4** 2013-09-27 11:29**MOT test number** 615020673222**Result** ✓ Passed**MOT #3** 2012-09-28 10:04**MOT test number** 197522472209**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** N/s/f seat belt is twisted**MOT #2** 2012-01-16 14:25**MOT test number** 675106212042**Result** ✓ Passed



MOT #1	2012-01-16 14:25
MOT test number	427596812000
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	DN58OVZ
Plate since	2019-03-28
Current registration	DN58OVZ
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2009-02-26
Last registration	2023-06-28
Complete history	See info



Registration #1	2009-02-26	26 mi
Registration #2	2012-01-16	36.406 mi
Registration #3	2012-09-28	38.735 mi
Registration #4	2013-09-27	43.339 mi
Registration #5	2014-09-13	48.316 mi
Registration #6	2015-09-17	53.894 mi
Registration #7	2015-09-17	53.894 mi
Registration #8	2016-08-30	59.376 mi
Registration #9	2016-08-30	59.376 mi
Registration #10	2017-09-21	64.732 mi
Registration #11	2017-09-22	64.732 mi
Registration #12	2018-09-17	69.811 mi
Registration #13	2019-09-14	74.488 mi
Registration #14	2020-09-28	79.567 mi
Registration #15	2021-09-28	84.646 mi
Registration #16	2022-09-28	89.725 mi
Registration #17	2023-06-28	94.804 mi
Registration #18	2023-06-28	94.804 mi
Registration #19	2023-06-28	94.804 mi
Registration #20	2023-06-28	94.804 mi
Registration #21	2023-06-28	94.804 mi
Registration #22	2023-06-28	94.804 mi
Registration #23	2023-06-28	94.804 mi
Registration #24	2023-06-28	94.804 mi
Registration #25	2023-06-28	94.804 mi
Registration #26	2023-06-28	94.804 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1922 mm
Height	1481 mm
Length	3958 mm
Wheel base	2489 mm
Kerb weight	966 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9J10615