

Ford



General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Black
Year of manufacture	2012
Top speed	124 mph
0 - 100 km/h	11.1 seconds
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 161 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 1

Date


2021-06-07

Pictures

Listing price

View report

9



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-09
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	21
Total items failed	2

MOT #12	2023-05-10 09:30	
MOT test number	174054686861	
Result	✓ Passed	
Next expiry date 2024-05		
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)))	

MOT #11		2023-05-10 09:30
MOT test number		736742986664
Result		🗙 Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Nearside Front Tyre tread depth below requirements	s of 1.6mm (5.2.3 (e))
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))		

MOT #10		2022-07-18 06:10
MOT test	number	839970563626
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #9		2022-07-15 10:25
MOT test	number	230059235478
Result		🗙 Failed
MAJOR the ingress	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, is of dirt (6.1.7 (g) (ii))	no longer prevents
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8	2021-07-15 15:36
MOT test number	248367970943
Result	✓ Passed

MOT #7	2019-07-02 08:25
MOT test number	976333692778
Result	✓ Passed
Advice Nearside Front Side repeater slightly discoloured (4.4.3	(a))
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i	i))

MOT #6	2018-07-10 14:40
MOT test number	976720784080
Result	✓ Passed





MOT #5		2018-07-10 08:40
MOT test I	number	911754286511
Result		🗙 Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Nearside Front Side repeater not working (4.4.1 (a) (ii))	
MAJOR	Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR ingress of	Offside Front Drive shaft joint constant velocity boot split or insecure, no long dirt (6.1.7 (g) (ii))	er prevents the

MOT #4	2017-06-26 14:26
MOT test number	638720604059
Result	✓ Passed

МОТ #3	2017-06-26 10:21
MOT test number	449299996012
Result	🗙 Failed

Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #2		2016-06-21 09:33
MOT test	number	913625938365
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2015-07-10 14:57
MOT test number	249971995487
Result	✓ Passed
Notice Off side rear tyre feathered on inner edge	



Tax & MOT check

Tax due: 1 January 2025	✓ Taxed	Expires: 9 May 2024	✓ МОТ
Tax status			Valid until 1 January
Days left			247
MOT expiry date			9 May 2024
Full MOT history			<u>See MOT history</u>
Tax calculation			

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-13
Last registration	2023-05-10
Complete history	See info



Registration #1	2012-09-13	9 mi
Registration #2	2015-07-10	14.038 mi
Registration #3	2016-06-21	21.623 mi
Registration #4	2017-06-26	33.791 mi
Registration #5	2017-06-26	33.791 mi
Registration #6	2018-07-10	45.830 mi
Registration #7	2018-07-10	45.830 mi
Registration #8		11.777 esi
Registration #8 Registration #9		11.517 est 11.517 est
-		10.000 est 00.000 est 00.000 est
Registration #9		10.000 est 10.000 est 10.000 est 10.000 est
Registration #9 Registration #10		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10 Registration #11		10.000 est 10.000 est 10.000 est 10.000 est 10.000 est 10.000 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1884 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1631 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 12/12